


# Service Record Details

For your  
2001 Tacoma

VIN:5TEPM62N91Z738959

**MILEAGE:**172,044



<b>Date of Service</b>	<b>SERVICE TYPE</b>	<b>Customer</b>
5/2013	Dealer	D Palm

Job	DATE	Operation	Payment
1	5/2013	<b>MULTI-POINT INSPECION *****</b>  MULTI-POINT INSPECION ***** - - - -THE TECH NOTED THAT THE DRIVERS SIDE PARKING BRAKE BELL CRANK IS SIEZED AND IN NEED OF REPLACEMENT. QOUTED 275.00 INSTALLED. CUSTOMER DECLINED AT THIS TIME. - -COMPLETED COURTESY MULTI-POINT INSPECTION CHECKED & MEASURED BRAKE PADS & TIRES.TESTED COOLANT & BATTERY. CHECKED SUSPENSION, AXLES, FILTERS, BELTS, HOSES, WIPER BLADES,HORN, LIGHTS, & WIPER BLADES.	Customer Pay
2	5/2013	<b>MARKER LIGHTS</b>  MARKER LIGHTS - -CUSTOMER REQUEST LEFT FRONT MARKER BULB REPLACEMENT . QOUTED 2.50 - -THE TECH INSTALLED THE LEFT FRONT MARKER BULB AS NEEDED. HAVE A GREAT NIGHT.	Customer Pay
3	5/2013	<b>RECALLS / CAMPAIGNS</b>  RECALLS / CAMPAIGNS - -COV SPARE TIRE CARRIER LIFT PLATE. - -THE TECH COMPLETED THE SERVICE AS NEEDED. HAVE A GREAT NIGHT.	Warranty Pay