



Service History for 2001 4Runner

Vehicle 2001 4Runner
VIN JT3HN86R419049390
Customer D PALM

DATE	SERVICE TYPE	SERVICE PROVIDER	MILEAGE	DESCRIPTION
2/16/09	Dealer	Ira Toyota of Manchester	123,019	Repair Order Number: 0418 CUSTOMER REQUESTS 5,000 MAINTENANCE INTERVAL TO ***CUSTOMER IS AWARE OF ADDITIONAL RECCOMENDAT VISIT, PERFORM 27 POINT C INSPECTION, INSPECTION F PLEASE SEE YOU, ***BRAKE! ***TIRES ARE 8/32***, TECH NEED FRONT BRAKES,\$485 A E BRKAES IBN REAR SIEZ, .
10/24/08	Dealer	Ira Toyota of Manchester	120,236	Repair Order Number: 0409 PERFORMED 27 POINT COU INSPECTION SHEET ATTACH REQUESTS THE REPLACEMEN FILTER, CUSTOMER DECLINE

5/14/08	Dealer	Ira Toyota of Manchester	115,226	Repair Order Number: 0392 CUSTOMER REQUESTS A VAL SYNTHETIC OIL CHANGE (M/ PERFORMED NEW HAMPSHI INSPECTION VEHICLE PASSE NEW HAMPSHIRE MOTOR VI INSPECTION VEHICLE PASSE INJECTION SERVICE3, REPLA BRAKE LIGHT
10/26/07	Dealer	Ira Toyota of Manchester	109,830	Repair Order Number: 0373 CUSTOMER REQUEST 5,000 I CHANGE,TIRE ROTATION,CH REPLACED AIR FULE RATIO S CUSTOMER REQUESTS THE F THE AIR FILTER
6/11/07	Dealer	Ira Toyota of Manchester	105,004	Repair Order Number: 0359 COMPLEETD DIAGNOSTICS-I SENSOR ONE HAS FAILED-AI CUSTOMER=CUST
5/10/07	Dealer	Ira Toyota of Manchester	103,937	Repair Order Number: 0355 CUSTOMER REQUESTS A LUE CHANGE, PERFORMED NEW MOTOR VEHICLE INSPECTIO PERFORMED NEW HAMPSHI OBD INSPECTION VEHICLE F REQUESTS TIMING BELT REF REPLACED LEAKING WATER I THERMOSTAT/REPLACED WC WHILE APART, REPLACED LE RT REAR TIRE=NO OTHER LE

11/15/06	Dealer	Ira Toyota of Manchester	99,283	Repair Order Number: 0339 CUSTOMER REQUESTS A LUE CHANGE, REPLACE SPARK PL COOLANT SERVICE DRAIN A AND REFILL AUTOMATIC TR/
5/24/06	Dealer	Ira Toyota of Manchester	93,318	Repair Order Number: 0322 PERFORMED NEW HAMPSHI INSPECTION VEHICLE PASSE DONUT PROMO WITH \$10.0 PERFORMED NEW HAMPSHI OBD INSPECTION VEHICLE F PERFORMED TIRE ROTATION OIL AND FILTER CHANGE, RE AND REAR DIFFERENTIAL AN FLUIDS
3/7/06	Dealer	Ira Toyota of Manchester	88,682	Repair Order Number: 0314 CUSTOMER REQUESTS A LUE CHANGE, PERFORMED COUF THIS VEHICLE SEE BELOW LI AND REPAIRS, PERFORMED SERVICE AND FLUID CHANG FILTER AND CLEANED DEBRI CLEANED AND LUBED THRO RECHECKED OPERATION, RE TAIL LIGHT BULB