



Your AutoCheck Vehicle History Report

Report run: 03/29/2021 14:28:15 EDT



2012 Volkswagen Jetta TDI

Wagon 4D (2.0L I4 DI)

VIN: 3VWPL7AJ3CM636318

Class: Mid Range Car -
Standard

Country of Assembly: Mexico

Vehicle Age: 9 year(s)

This vehicle is AutoCheck Assured™



This vehicle does not have any [state title brands](#) or other major problems reported.

YOUR VEHICLE AT A GLANCE

- ✓ No State Title Brand Reported
- ✓ No Accident Reported
No Air Bag Deployed
- ✓ No Other Damage Reported
- ✓ No Specific Event Reported
- ✓ No Odometer Problem(s) Reported
Last Odometer Reading: 186,805
- ✓ No Open Recall(s) Reported
- i Service & Repair Information Reported



ONE OWNER

Calculated Owners: **1**

Owner History



Current Owner

Purchased: 2012
Where: RI
Owned from: 01/26/2012 - Present

Vehicle Usage



Vehicle Use: There is indication of the below usage(s) for this vehicle
Personal | Fleet | Rental | Lease | Taxi | Livery | Police | Government | Drivers Ed | Commercial

Major State Title Brand Check



Your Vehicle Checks Out: No major state title brand has been reported by the state Division of Motor Vehicles (DMV).

0 Problem(s) Reported	Major State Title Areas Checked
	No fire brand
	No hail brand
	No flood brand
	No junk or scrapped brand
	No manufacturer buyback
	No lemon brand
	No salvage brand
	No rebuilt or rebuildable brand



Accident Check



Your Vehicle Checks Out: AutoCheck has not received any accident records from government sources and independent agencies on this vehicle. Not all accidents are reported to AutoCheck.



NO ACCIDENT
FOUND ON RECORD

Damage Check



Your Vehicle Checks Out: AutoCheck has not received a damage-related event from an auction or an independent source. Not all damage events are reported to AutoCheck. It is recommended to have pre-owned vehicles inspected by a third party prior to purchase.



NO DAMAGE
FOUND ON RECORD

0 Problem(s) Reported

Other Problem Areas Checked



No non-title fire damaged record



No non-title hail damaged record



No non-title flood damaged record



No auction junk or scrapped record



No auction rebuilt or rebuildable record



No salvage auction record



No damaged or major damage incident record



No structural damage or structural alteration record



No recycling facility record



No crash test record

Other Title Brand And Specific Event Check



Your Vehicle Checks Out: No Non-major state title brand(s) and/or additional significant event(s) has been reported to AutoCheck.

0 Event(s) Reported

Vehicle Events Checked



No Insurance Loss record



No Titled to an insurance company record



No Auction Lemon/Manufacturer Buyback record



No abandoned title record



No grey market title record



No loan/lien record(s)



No repossessed record



No corrected title record



No duplicate title record



No theft record(s)

Odometer Check



Your Vehicle Checks Out: No odometer brands, rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.



State title odometer check



Auction odometer check



Odometer calculation check

0 Problem(s) Reported

Mileage





















Date Reported











Other



143

02/24/2012

	65,313	10/03/2014
	70,338	12/11/2014
	78,638	04/11/2015
	78,769	04/20/2015
	94,096	11/18/2015
	97,671	01/11/2016
	122,838	12/17/2016
	131,924	03/29/2017
	132,413	04/05/2017
	133,096	04/14/2017
	138,000	06/14/2017
	151,494	11/27/2017
	152,534	01/02/2018
	152,535	01/23/2018
	155,227	02/17/2018
	159,339	04/30/2018
	160,410	05/21/2018
	163,476	07/31/2018
	164,422	08/27/2018
	164,789	09/14/2018

	165,292	09/28/2018
	170,286	05/04/2019
	172,615	07/01/2019
	174,464	08/27/2019
	177,552	11/30/2019
	178,382	12/17/2019
	179,492	01/21/2020
	186,710	10/08/2020
	186,801	10/15/2020
	186,805	11/05/2020

Open Recall Check



Your Vehicle Checks Out: AutoCheck found no open recalls reported by the vehicle manufacturer. Not all open recalls are reported to AutoCheck.

Service And Repair History Check



Information Reported: There have been some service and repair information reported from dealers or service shops.

Date of Service	Location	Source	Service Type
10/03/2014	RI	Balise volkswagen 401.352.5912	FUEL SYSTEM SERVICED HEAT OR AIR CONDITIONING SERVICED MULTIPLE POINT VEHICLE INSPECTION TIRES OR WHEELS SERVICE PERFORMED LUBE, OIL AND/OR FILTER CHANGED VEHICLE FLUIDS SERVICED
12/11/2014	RI	Balise volkswagen 401.352.5912	MULTIPLE POINT VEHICLE INSPECTION TIRES OR WHEELS SERVICE PERFORMED VEHICLE SERVICED
04/11/2015	RI	Balise	COOLING SYSTEM SERVICED

		volkswagen 401.352.5912	HEAT OR AIR CONDITIONING SERVICED MULTIPLE POINT VEHICLE INSPECTION RECOMMENDED MAINTENANCE PERFORMED BRAKES SERVICED LIGHTS OR SIGNALS SERVICED TIRES OR WHEELS SERVICE PERFORMED LUBE, OIL AND/OR FILTER CHANGED VEHICLE SERVICED VEHICLE FLUIDS SERVICED
04/20/2015	RI	Balise volkswagen 401.352.5912	MULTIPLE POINT VEHICLE INSPECTION
11/18/2015	RI	Independent Repair Center	LUBE, OIL AND/OR FILTER CHANGED
01/11/2016	RI	Independent Repair Center	TIRES OR WHEELS SERVICE PERFORMED
12/17/2016	RI	Balise volkswagen 401.352.5912	STEERING SYSTEM SERVICED COOLING SYSTEM SERVICED FUEL SYSTEM SERVICED AIR FILTER CHANGED BATTERY SERVICED OR REPLACED MULTIPLE POINT VEHICLE INSPECTION RECOMMENDED MAINTENANCE PERFORMED EXHAUST SYSTEM SERVICED TRANSMISSION REPLACED BRAKES SERVICED DRIVE LINE SERVICED ELECTRICAL SYSTEM SERVICED LIGHTS OR SIGNALS SERVICED TIRES OR WHEELS SERVICE PERFORMED LUBE, OIL AND/OR FILTER CHANGED VEHICLE SERVICED VEHICLE FLUIDS SERVICED
03/29/2017	RI	Balise volkswagen 401.352.5912	MULTIPLE POINT VEHICLE INSPECTION
04/05/2017	RI	Independent Repair Center	BATTERY SERVICED OR REPLACED BRAKES SERVICED
04/14/2017	RI	Independent Repair Center	MULTIPLE POINT VEHICLE INSPECTION LUBE, OIL AND/OR FILTER CHANGED
06/14/2017	RI	Independent Repair Center	TIRES OR WHEELS SERVICE PERFORMED
06/16/2017	RI	Independent Repair Center	TIRES OR WHEELS SERVICE PERFORMED
11/27/2017	RI	Independent Repair Center	VEHICLE SERVICED
01/02/2018	RI	Balise volkswagen 401.352.5912	FUEL SYSTEM SERVICED ENGINE SERVICED RECOMMENDED MAINTENANCE PERFORMED LIGHTS OR SIGNALS SERVICED LUBE, OIL AND/OR FILTER CHANGED VEHICLE SERVICED

01/23/2018		Manufacturer	DIESEL EMISSION SYSTEM HAS BEEN REPORTED AS REPAIRED AND IN COMPLIANCE WITH FEDERAL GOVERNMENT STANDARDS
02/17/2018	RI	Balise volkswagen 401.352.5912	EMISSION SYSTEM SERVICED TIRES OR WHEELS SERVICE PERFORMED
04/30/2018	RI	Balise volkswagen 401.352.5912	MULTIPLE POINT VEHICLE INSPECTION DRIVE LINE SERVICED
05/21/2018	RI	Independent Repair Center	COOLING SYSTEM SERVICED ENGINE SERVICED
07/31/2018	RI	Independent Repair Center	STARTING OR CHARGING SYSTEM SERVICE PERFORMED
08/27/2018	RI	Balise volkswagen 401.352.5912	MULTIPLE POINT VEHICLE INSPECTION
09/14/2018	RI	Balise volkswagen 401.352.5912	RECOMMENDED MAINTENANCE PERFORMED ELECTRICAL SYSTEM SERVICED STARTING OR CHARGING SYSTEM SERVICE PERFORMED LIGHTS OR SIGNALS SERVICED
09/28/2018	RI	Balise volkswagen 401.352.5912	MULTIPLE POINT VEHICLE INSPECTION
05/04/2019	RI	Balise volkswagen 401.352.5912	MULTIPLE POINT VEHICLE INSPECTION LUBE, OIL AND/OR FILTER CHANGED
07/01/2019	RI	Balise volkswagen 401.352.5912	MULTIPLE POINT VEHICLE INSPECTION LIGHTS OR SIGNALS SERVICED
08/27/2019	RI	Balise volkswagen 401.352.5912	MULTIPLE POINT VEHICLE INSPECTION
11/30/2019		Balise volkswagen 401.352.5912	COOLING SYSTEM SERVICED MULTIPLE POINT VEHICLE INSPECTION ELECTRICAL SYSTEM SERVICED
12/17/2019		Balise volkswagen 401.352.5912	MULTIPLE POINT VEHICLE INSPECTION
01/21/2020		Balise volkswagen 401.352.5912	MULTIPLE POINT VEHICLE INSPECTION
10/08/2020	RI	Balise volkswagen 401.352.5912	MULTIPLE POINT VEHICLE INSPECTION

10/15/2020	RI	Balise volkswagen 401.352.5912	STEERING SYSTEM SERVICED MULTIPLE POINT VEHICLE INSPECTION ELECTRICAL SYSTEM SERVICED LIGHTS OR SIGNALS SERVICED
11/05/2020	RI	Balise volkswagen 401.352.5912	VEHICLE SERVICED

Detailed Vehicle History

Below are the historical events for this vehicle listed in chronological order. Any discrepancies will be in bold text.

Report Run Date: 03/29/2021 14:28:15 EDT

Vehicle: 2012 Volkswagen Jetta TDI (3VWPL7AJ3CM636318)

Event Date	Location	Odometer Reading	Data Source	Details
11/05/2011	MA		Independent Source	VEHICLE MANUFACTURED AND SHIPPED TO DEALER
01/16/2012			Independent Source	VEHICLE MANUFACTURED AND SHIPPED TO DEALER
01/26/2012	WARWICK, RI		Motor Vehicle Dept.	TITLE
01/26/2012	WARWICK, RI		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL
02/24/2012	WARWICK, RI	143	Motor Vehicle Dept.	TITLE
08/09/2013	WARWICK, RI		Motor Vehicle Dept.	TITLE REGISTRATION EVENT/RENEWAL
10/03/2014	WEST WARWICK, RI	65,313	Balise volkswagen 401.352.5912	FUEL SYSTEM SERVICED HEAT OR AIR CONDITIONING SERVICED MULTIPLE POINT VEHICLE INSPECTION TIRES OR WHEELS SERVICE PERFORMED LUBE, OIL AND/OR FILTER CHANGED VEHICLE FLUIDS SERVICED
12/11/2014	WEST WARWICK, RI	70,338	Balise volkswagen 401.352.5912	MULTIPLE POINT VEHICLE INSPECTION TIRES OR WHEELS SERVICE PERFORMED VEHICLE SERVICED
04/11/2015	WEST WARWICK, RI	78,638	Balise volkswagen 401.352.5912	COOLING SYSTEM SERVICED HEAT OR AIR CONDITIONING SERVICED MULTIPLE POINT VEHICLE INSPECTION RECOMMENDED MAINTENANCE PERFORMED BRAKES SERVICED LIGHTS OR SIGNALS SERVICED TIRES OR WHEELS SERVICE PERFORMED LUBE, OIL AND/OR FILTER CHANGED VEHICLE SERVICED VEHICLE FLUIDS SERVICED
04/20/2015	WEST	78,769	Balise	MULTIPLE POINT VEHICLE INSPECTION

WARWICK,
RIvolkswagen
401.352.5912

09/18/2015	WARWICK, RI		Motor Vehicle Dept.	TITLE
09/18/2015	WARWICK, RI		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL
11/18/2015	WARWICK, RI	94,096	Independent Repair Center	LUBE, OIL AND/OR FILTER CHANGED
01/11/2016	WARWICK, RI	97,671	Independent Repair Center	TIRES OR WHEELS SERVICE PERFORMED
12/17/2016	WEST WARWICK, RI	122,838	Balise volkswagen 401.352.5912	STEERING SYSTEM SERVICED COOLING SYSTEM SERVICED FUEL SYSTEM SERVICED AIR FILTER CHANGED BATTERY SERVICED OR REPLACED MULTIPLE POINT VEHICLE INSPECTION RECOMMENDED MAINTENANCE PERFORMED EXHAUST SYSTEM SERVICED TRANSMISSION REPLACED BRAKES SERVICED DRIVE LINE SERVICED ELECTRICAL SYSTEM SERVICED LIGHTS OR SIGNALS SERVICED TIRES OR WHEELS SERVICE PERFORMED LUBE, OIL AND/OR FILTER CHANGED VEHICLE SERVICED VEHICLE FLUIDS SERVICED
03/29/2017	WEST WARWICK, RI	131,924	Balise volkswagen 401.352.5912	MULTIPLE POINT VEHICLE INSPECTION
04/05/2017	WARWICK, RI	132,413	Independent Repair Center	BATTERY SERVICED OR REPLACED BRAKES SERVICED
04/14/2017	WARWICK, RI	133,096	Independent Repair Center	MULTIPLE POINT VEHICLE INSPECTION LUBE, OIL AND/OR FILTER CHANGED
06/14/2017	WARWICK, RI	138,000	Independent Repair Center	TIRES OR WHEELS SERVICE PERFORMED
06/16/2017	WARWICK, RI		Independent Repair Center	TIRES OR WHEELS SERVICE PERFORMED
09/01/2017	WARWICK, RI		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL
11/27/2017	WARWICK, RI	151,494	Independent Repair	VEHICLE SERVICED

Center

01/02/2018	WEST WARWICK, RI	152,534	Balise volkswagen 401.352.5912	FUEL SYSTEM SERVICED ENGINE SERVICED RECOMMENDED MAINTENANCE PERFORMED LIGHTS OR SIGNALS SERVICED LUBE, OIL AND/OR FILTER CHANGED VEHICLE SERVICED
01/23/2018		152,535	Manufacturer	DIESEL EMISSION SYSTEM HAS BEEN REPORTED AS REPAIRED AND IN COMPLIANCE WITH FEDERAL GOVERNMENT STANDARDS
02/17/2018	WEST WARWICK, RI	155,227	Balise volkswagen 401.352.5912	EMISSION SYSTEM SERVICED TIRES OR WHEELS SERVICE PERFORMED
04/30/2018	WEST WARWICK, RI	159,339	Balise volkswagen 401.352.5912	MULTIPLE POINT VEHICLE INSPECTION DRIVE LINE SERVICED
05/21/2018	WARWICK, RI	160,410	Independent Repair Center	COOLING SYSTEM SERVICED ENGINE SERVICED
07/31/2018	WARWICK, RI	163,476	Independent Repair Center	STARTING OR CHARGING SYSTEM SERVICE PERFORMED
08/27/2018	WEST WARWICK, RI	164,422	Balise volkswagen 401.352.5912	MULTIPLE POINT VEHICLE INSPECTION
09/14/2018	WEST WARWICK, RI	164,789	Balise volkswagen 401.352.5912	RECOMMENDED MAINTENANCE PERFORMED ELECTRICAL SYSTEM SERVICED STARTING OR CHARGING SYSTEM SERVICE PERFORMED LIGHTS OR SIGNALS SERVICED
09/28/2018	WEST WARWICK, RI	165,292	Balise volkswagen 401.352.5912	MULTIPLE POINT VEHICLE INSPECTION
05/04/2019	WEST WARWICK, RI	170,286	Balise volkswagen 401.352.5912	MULTIPLE POINT VEHICLE INSPECTION LUBE, OIL AND/OR FILTER CHANGED
07/01/2019	WEST WARWICK, RI	172,615	Balise volkswagen 401.352.5912	MULTIPLE POINT VEHICLE INSPECTION LIGHTS OR SIGNALS SERVICED
08/04/2019	WARWICK, RI		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL
08/27/2019	WEST WARWICK, RI	174,464	Balise volkswagen 401.352.5912	MULTIPLE POINT VEHICLE INSPECTION
11/30/2019		177,552	Balise	COOLING SYSTEM SERVICED

volkswagen
401.352.5912MULTIPLE POINT VEHICLE INSPECTION
ELECTRICAL SYSTEM SERVICED

12/17/2019		178,382	Balise volkswagen 401.352.5912	MULTIPLE POINT VEHICLE INSPECTION
01/21/2020		179,492	Balise volkswagen 401.352.5912	MULTIPLE POINT VEHICLE INSPECTION
10/08/2020	WEST WARWICK, RI	186,710	Balise volkswagen 401.352.5912	MULTIPLE POINT VEHICLE INSPECTION
10/15/2020	WEST WARWICK, RI	186,801	Balise volkswagen 401.352.5912	STEERING SYSTEM SERVICED MULTIPLE POINT VEHICLE INSPECTION ELECTRICAL SYSTEM SERVICED LIGHTS OR SIGNALS SERVICED
11/05/2020	WEST WARWICK, RI	186,805	Balise volkswagen 401.352.5912	VEHICLE SERVICED

This Vehicle's Glossary

Below are the specific definitions for events that appear in this vehicle's report. More information is available in the full [AutoCheck glossary](#).

Term	Section Location	Definition
Personal Use	Vehicle Use	This vehicle was driven for personal use.

AutoCheck Terms and Conditions

This report, and any reliance upon it, is subject to [AutoCheck Terms and Conditions](#). If you obtained the report from a lender/dealer, the lender/dealer has been provided with these Terms and Conditions and can share them with you. These AutoCheck Terms and Conditions are also available at any time at www.autocheck.com/terms or by writing to Experian: Experian Automotive C/O AutoCheck Customer Service 955 American Lane Schaumburg, IL 60173.

About AutoCheck

AutoCheck vehicle history reports by Experian Automotive is the leading vehicle history reporting service. With expert data handling, the Experian Automotive database houses over 4 billion records on a half a billion vehicles. Every AutoCheck vehicle history report will give you confidence when buying or selling your next used vehicle, with superior customer service every step of the way.

Patent Notice

Certain aspects of this vehicle history report may be covered by U.S. Patent 8,005,759.