

Service Record Details

For your
2006 Tundra

VIN:5TBDT44156S519370

MILEAGE:110,230



Date of Service
3/2017

SERVICE TYPE
Dealer

Customer
D Palm

Job	DATE	Operation	Payment
1	3/2017	FACTORY LOF - PERFORM OIL CHANGE (UP TO 5 QTS CONVENTIONAL FLUID), REPLACE FACTORY OIL FILTER, TO - -FACTORY LOF - PERFORM OIL CHANGE (UP TO 5 QTS CONVENTIONAL FLUID), REPLACE FACTORY OIL FILTER, TOP FLUIDS, RESET MAINTENANCE LIGHT - - - -110230 CHANGE ENGINE OIL AND FILTER, TOP OFF FLUIDS	Customer Pay
2	3/2017	C.S LUB THE DRIVESHAFT C.S LUB THE DRIVESHAFT - -C.S LUB THE DRIVESHAFT - - - -110230 LUBED DRIVESHAFT.	Customer Pay
3	3/2017	CUSTOMER REQUESTS DO NOT PERFORM MULTI-POINT INSPECTION CUSTOMER REQUESTS DO NOT PERFORM MULTI-POINT INSPECTION - -CUSTOMER REQUESTS DO NOT PERFORM MULTI-POINT INSPECTION - - - -110230 DID NOT PERFORM MPI. VEHICLE HAD A FLASHING TPMS LIGHT UPON ARRIVAL.	Customer Pay
4	3/2017	PERFORM STATE INSPECTION PERFORM STATE INSPECTION - -PERFORM STATE INSPECTION - - - -110230 MSI DONE	Customer Pay