

Service Record Details

For your

2006 Tundra

VIN:5TBDT44156S519370

MILEAGE:99,972



Date of Service

3/2016

SERVICE TYPE

Dealer

Customer D Palm

Job	DATE	Operation	Payment
1	3/2016	OIL AND FILTER - CHANGE ~ ~OIL AND FILTER - CHANGE ~ ~	Customer Pay
2	3/2016	CUSTOMER REQUESTS DO NOT PERFORM MULTI-POINT INSPECTION CUSTOMER REQUESTS DO NOT PERFORM MULTI-POINT INSPECTION - -CUSTOMER REQUESTS	Customer Pay

DO NOT PERFORM MULTI-POINT INSPECTION ~ |~