

Service Record Details

For your
2006 Tundra

VIN:5TBDT44156S519370

MILEAGE:134,541



Date of Service	SERVICE TYPE	Customer
10/2019	Dealer	D Palm

Job	DATE	Operation	Payment
1	10/2019	SERVICE - 10,000 MILES OR 12 MONTHS SERVICE - 10,000 MILES OR 12 MONTHS ~ ~SERVICE - 10,000 MILES OR 12 MONTHS ~ ~ ~ ~134541 COMPLETED SERVICE	Customer Pay
2	10/2019	SHOCKS/STRUTS (BOTH FRONT) - REPLACE SHOCKS/STRUTS (BOTH FRONT) - REPLACE ~ ~ ~ ~,CUSTOMER DECLINED SERVICE	Customer Pay