

# Service Record Details

For your  
2006 Tundra

VIN:5TBDT44156S519370      **MILEAGE:**52,498

<b>Date of Service</b>	<b>SERVICE TYPE</b>	<b>Customer</b>
6/2011	Dealer	D Palm

Job	DATE	Operation	Payment
1	6/2011	<b>LOF</b>  LOF ~ ~OIL AND FILTER CHANGE, CHECK AND TOP OFF ALL FLUIDS AND SET TIRE PRESSURES ~  ~OIL AND FILTER CHANGE TOPP OFF FLUIDS AND ROTATE TIRES,SET TIRE PRESSURE ~  ~COMPLETE	<b>Customer Pay</b>
2	6/2011	<b>MULTIPOINT INSPECT</b>  MULTIPOINT INSPECT ~ ~ ~ ~ ~ ~PERFORMED MULTIPOINT INSPECTION. TIRE LIGHT WAS FLASHING BEFORE SERVICE WAS PERFORMED.	<b>Customer Pay</b>