

Service Record Details

For your
2006 Tundra

VIN:5TBDT44156S519370

MILEAGE:132,292

Date of Service
2/2019

SERVICE TYPE
Dealer

Customer
D Palm

Job	DATE	Operation	Payment
1	2/2019	REPLACE BATTERY WITH 48 MONTH FULL REPLACEMENT WARRANTY REPLACE BATTERY WITH 48 MONTH FULL REPLACEMENT WARRANTY ~ ~MULTI-POINT VEHICLE INSPECTION ~ ~ ~ ~132292 OK	Customer Pay
2	2/2019	DIAGNOSE MALFUNCTION LIGHT DIAGNOSE MALFUNCTION LIGHT ~ ~ ~ ~,CUSTOMER DECLINED SERVICE	Customer Pay
3	2/2019	BATTERY BATTERY ~ ~C.S TRUCK NEEDED MULTIPLE JUMP STARTS BATTERY REPLACEMENT BATTERY ORIGINALLY REPLACED RO#666633 3/7/14 ~ ~C.S TRUCK NEEDED MULTIPLE JUMP STARFOUND FAILED BATTERY REPLACED BATTERY ~ ~132292 FOUND FAULTY BATTERY INTER FAIL TESTED BATTERY. FAILED TEST. REPLACED WITH 27F60. FAILED CODE G50A-E0HR7-MA0MC	Warranty Pay