

# Service Record Details

For your  
2006 Tundra

VIN:5TBDT44156S519370

**MILEAGE:**48,334



<b>Date of Service</b> 10/2010	<b>SERVICE TYPE</b> Dealer	<b>Customer</b> D Palm
-----------------------------------	-------------------------------	---------------------------

Job	DATE	Operation	Payment
1	10/2010	<b>MULTIPOINT INSPECT</b>  MULTIPOINT INSPECT ~ ~ ~ ~ ~ ~ -I DID MULTI POINT CHECK. TIRE PRESSURE LIGHT IS FLASHING- ISSUE WITH SENSOR BRAKE FLUID WAS LITTLE LOW-FILLED TO PROPER LEVEL	<b>Customer Pay</b>
2	10/2010	<b>OIL &amp; FILTER SVC</b>  OIL & FILTER SVC ~ ~ -CUSTOMER REQUEST: PERFORM OIL & FILTER SERVICE ~ ~ -CHANGE ENGINE OIL AND FILTER, INSPECT FLUID LEVELS, INSPECT TIRE WEAR AND RESET TIRE PRESSURES, CHECK OPERATION OF ALL LIGHTS AND CONTROLS, LUBRICATE ALL HIDGES AND LATCHES, INSPECT FRONT AND REAR BRAKES FOR WEAR, INSPECT SUSPENSION COMPONENTS, TIE ROD END ~ ~ ~AND UNDERBODY, INSPECT COOLING SYSTEM HOSES/CONNECTIONS AND COOLANT CONDITION, INSPECT DRIVE BELTS, PERFORM MULTIPOINT INSPECTION INCLUDING BATTERY TEST, FILL OUT REPORT.	<b>Customer Pay</b>
3	10/2010	<b>WHEEL &amp; TIRE</b>  WHEEL & TIRE ~ ~ -C/S PLEASE SWAP FRONT TIRES SIDE TO SIDE ~ ~ ~ ~ -I SWAPPED FRONT TIRES SIDE TO SIDE.	<b>Customer Pay</b>