Service Record Details

For your

2006 Tundra

VIN:5TBDT44156S519370

MILEAGE:46,263

ate of Service /2010		SERVICE TYPE Dealer	Customer D Palm	
Job	DATE	Operation		Payment
1	6/2010	OIL & FILTER SVC		Customer Pay
		OIL & FILTER SVC ~ ~CUSTOMER REQUEST: PERFORM OIL & FILTER SERVICE ~ ~CHANGE ENGINE OIL AND FILTER, INSPECT FLUID LEVELS,INSPECT TIRE WEAR AND RESET TIRE PRESSURES, CHECK OPERATION OF ALL LIGHTS AND CONTROLS, LUBRICATE ALL HIDGES AND LATCHES, INSPECT FRONT AND REAR BRAKES FOR WEAR, INSPECT SUSPENSION COMPONENTS, TIE ROD END ~ ~AND UNDERBODY, INSPECT COOLING SYSTEM HOSES/CONNECTIONS AND COOLANT CONDITION, INSPECT DRIVE BELTS, PERFORM MULTIPOINT INSPECTION INCLUDING BATTERY TEST, FILL OUT REPORT.		¢

Customer Pay

2 6/2010 MULTIPOINT INSPECT

MULTIPOINT INSPECT ~|~ ~|~ ~|~ PROBLEM WITH TPS CUSTOMER AWARE