

Service Record Details

For your
2006 Tundra

VIN:5TBDT44156S519370 MILEAGE:44,669

Date of Service	SERVICE TYPE	Customer
3/2010	Dealer	D Palm

Job	DATE	Operation	Payment
1	3/2010	STATE INSPECTION STATE INSPECTION ~ ~ ~ ~ ~ ~MSI COMPLETE	Customer Pay
2	3/2010	OIL & FILTER SVC OIL & FILTER SVC ~ ~CUSTOMER REQUEST: PERFORM OIL & FILTER SERVICE ~ ~CHANGE ENGINE OIL AND FILTER, INSPECT FLUID LEVELS,INSPECT TIRE WEAR AND RESET TIRE PRESSURES, CHECK OPERATION OF ALL LIGHTS AND CONTROLS, LUBRICATE ALL HIDGES AND LATCHES, INSPECT FRONT AND REAR BRAKES FOR WEAR, INSPECT SUSPENSION COMPONENTS, TIE ROD END ~ ~AND UNDERBODY, INSPECT COOLING SYSTEM HOSES/CONNECTIONS AND COOLANT CONDITION, INSPECT DRIVE BELTS, PERFORM MULTIPOINT INSPECTION INCLUDING BATTERY TEST, FILL OUT REPORT.	Customer Pay
3	3/2010	MULTIPOINT INSPECT MULTIPOINT INSPECT ~ ~ ~ ~FOUND TIRE PRESSURE LIGHT IS FLASHING	Customer Pay