

Service Record Details

For your
2006 Tundra

VIN:5TBDT44156S519370

MILEAGE:12,664



Date of Service
2/2007

SERVICE TYPE
Dealer

Customer
D Palm

Job	DATE	Operation	Payment
1	2/2007	PERFORMED LOWER BALL JOINT CAMPAIGN PERFORMED LOWER BALL JOINT CAMPAIGN ~ ~PERFORM LOWER BALL JOINT REPLACEMENT CAMPAIGN ~ ~T1=99,T2=99 ~ ~12664 COMPLETE	Warranty Pay