**AUTO SERVICE CENTERS** 

781-933-4000

Hogan keeps you rolling!

CASH SALE

Invoice Date Cust No. Page Invoice No. 05/04/2016 7 - 895803 1/1 850590

Mileage: 38,447

Time in 1:09 PM Time out 1:20 PM

2000 TOYOTA ECHO

■ Woburn

Sold To

Purchase

Ord. No.

Westwood

781-329-9090 Waltham 781-891-7350 Natick 508-655-6700

Sales

Person

Beverly 978-927-406 Lowell 978-458-660

www.hogantire.com

Other Phone

Hudson 978-568-0404

Visa 45.00 (EcHo) Ship To:

Main Phone

578 (978) 927-2015 Entered: 578 em No. Qty Qty Description F.E.T. **Price Net Extension** Ordered Shipped IAG DIAG/INSPECTION SERVICES... 1.00 CANAO 1.00 DIAGNOSTIC CHK ENG LIGHT SCAN/RESET 0.00 0.00 45.00 45.00 \*P0440 SM EVAP LEAK, CLEARED

Ship Via

ay Method		Amount	Signature	THE RESERVE OF THE PARTY OF THE
ISA	****2624	45.00	IP DAT	
			21 116	

recommend you return for a torque check after the first 10-50 miles when wheels are removed. See hogantire.com for warranty details. rporate Office: PO Box 2235, Woburn, Ma 01888 | 781-933-4004

Sub-Total Labor:

Terms: RET VIN: JTDBT1235Y0097074

45.00

Non-Taxable Amount:

45.00

Taxable Amount:

Total:

0.00

ustomer Authorization for Total

45.00

#### WINDHAM MOBIL BRAKE AND TIRE

54 HAVERHILL RD

Windham, NH 03087-0000 Shop Phone: (603) 818-8430 Fax: (603) 216-5193

Email: WINDMOBIL@COMCAST.NET Web Address: WWW.WINDHAMMOBIL.COM

Invoice

34963

Estimate Ref #36,520 Date Printed: 01/08/2015 Printed Time: 4:31 pm

Hat/Ref:

WINDHAM MOBIL SERVICE CENTER

Time Promised:

TA ECHO L4 1.5L 1497CC FI GAS N 1NZFE

8

Mileage In: 36,541

Date Written:

01/07/2015

Mileage Out: 36,580

Written By:

HIS R W

DOM:

Save Old Parts: No

Job Name	Description	Technician	Qty	List	Extended
Job #1	REPLACE EXHAUST BOLT AND SPRING	вов	2.00 2.00 1.00 1.50		
Part 4978	EXHAUST BOLT		2.00	8.94	17.88
Part 4979	EXHAUST SPRING			10.14	20.28
Part 9215	GASKET			12.38	12.38
Labor 1	Work Requested - REPLACE EXHAUS SPRING	ST BOLT AND		84.50	126.75
Work Performed - EXTRA	ACT ROTTED BOLTS FROM MANIFOLD				

Job #2	ENGINE MOUNT - Replace - Rear BOB Mount			
Part 1237123011	ENGINE MOUNT - Rear Mount - Auto Trans	1.00	64.42	64.42
Labor 1	Work Requested - ENGINE MOUNT - Replace - Rear Mount	0.80	84.50	67.60

#### "WE APPRECIATE ALL YOUR BUSINESS"

Payment Date	Type	Method	Amount
1/8/2015	Check	#7252	341.91
		Payment Totals:	\$341.91

Parts: \$114.96
Labor: \$194.35
Sublet: \$0.00
Misc: \$0.00
Hazmat: \$14.86
Supplies: \$17.74

Tax Total:

\$0.00 **\$341.91** 

Invoice Total: Less Paid: Balance Due:

341.91 \$0.00 9272015

665060

\*INVOICE\*

PAGE 1

Ta Toyota Scion

> 161 Andover St. \* Rt. 114 Danvers, MA 01923 978-739-8333 \* 800-230-0982 www.iramotorgroup.com

		SER	VICE ADVISOR:	6441 IL	ANA SNYDE	RMAN	
COLOR YEAR	MAKE/MODEL		VIN	LICENSE	MILEAGE	IN/ OUT	TA
ABSOLUTELY 00 TOY	OTA ECHO	JTDBT	1235Y0097074		18512	/18512	268.
DEL DATE PROD. DATE	WARR. EXP. PROMI	SED	PO NO.	DATE	PAYMENT	INV.	DATE
14NOV00 IS				85.00	CASH	24NOV	)6
LINE OPCODE TECH T A STATE INSPECTION	YPE HOURS			LIST	NET	TOT	TAL
LINE OPCODE TECH T				LIST	NET	TOT	CAL
SI STATE INSE 925 R	RODRIGUEZ, TROY LIC	#: /					
****	CT *******	*****	******	*****	29.00	29.	.00
	1	1111111	!!THANK YOU!! FOR	1111111	111111111	[141111	11
		CHO	OSING IRA MOT	OR GROU	P		
	<u> </u>	1111111	111111111111111	1111111	111111111	1111111	!





ALL PARTS INSTALLED ARE NEW OR FACTORY REBUILT UNLESS SPECIFIED OTHERWISE

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE BEYOND OUR CONTROL.

In addition to the charges for parts, labor, tax, etc., Ira Toyota Scion also charges a "shop charge" as part of the repair bill. This "shop charge" is to help defray the costs of certain materials that cannot be accurately itemized, but which are generally used in the repair and service of vehicles. These items include, but are not limited to, rags, bolts, screws, hand cleaner, small amounts of lubricant, etc. This charge is calculated as a percentage of the total labor charge.

Replacement parts and tires are warranted for defects in material or workmanship by the manufacturer.

Please present your receipt and the vehicle to our Service Department during normal business hours.

DESCRIPTION	TOTALS
LABOR AMOUNT	29.00
PARTS AMOUNT	0.00
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
SHOP CHARGE	0.00
TOTAL CHARGES	29.00
DISCOUNTS/DEDUCTIBLES	0.00
SALES TAX	0.00
PLEASE PAY THIS AMOUNT	29 00

9272015

6 1 8 3 7 9 \*INVOICE\* ra Toyota Scion

161 Andover St. \* Rt. 114 Danvers, MA 01923 978-739-8333 \* 800-230-0982 www.iramotorgroup.com

PAGE 1

SERVICE ADVISOR: 6757 JIM HOGAN

				SERV	TICE ADVISOR			attended to the selection	de la companya del companya de la companya del companya de la comp
COLOR	YEAR	MAKE/MODEL			VIN	LICENSI	E MILEAGE	IN/ OUT	TAG
ABSOLUTELY	00 TOY	OTA ECHO		JTDBT1	.235Y009707	4	17703	/17703	T272
DEL DATE	PROD. DAJE	WARR. EXP.	PROMIS	ED	PO NO.	HATE	PAYMENT	INV. D	ATE
14NOV00 IS				APR06		85.00	CASH	17APR06	5
			OPTIONS	STK:	TY4242 ENG	: 1NZ-FF			
08:35 17AP		46 17APR06	/ Y = 1			LIST	NET	TOTA	ΛT.
		FLOOR PANE	L FOR SU	RFACE R	UST, DETERM			1012	ш
WO	RK IS RE	EQUIRED. LO			11 N				
CAUSE: REC	THE COLD SECTION AND ADDRESS OF THE COLD SECTION AS A SEC	T FLOOR PA	NI AND AD	DT.V CEN	יידע סק.ד				
402014		APENELLI, S			MEK KII				
	W	TT45						(N/C	2)
		152 FLOOR						(N/C	
		3930-DS TER	OSTAT SE	ALER MS	5-9			(N/C	-)
CLAIM		cim. coomi.							
AUTH C	ODE:				- 4	No Service			
C/P PECALL	יייברט זייב	ERIFIED REC	ATT TECH	DEDEOR	MED DECAL				
C/K KECALL		*****					***		
B COURTESY					- Aw			1	
CI CO		NSPECTION	EDOTO T.	ан /	/ /				2
	6756 R	RAPENELLI,S ISP	ERGIO LI	C#: /				(N/C	7)
	****	******	*****	*****	*******	*****	*** //		
				1141111	!THANK YOU		/11111141/1	7111111	!
					FOR				

ALL PARTS INSTALLED ARE NEW OR FACTORY REBUILT UNLESS SPECIFIED OTHERWISE

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE BEYOND OUR CONTROL.

In addition to the charges for parts, labor, tax, etc., Ira Toyota Scion also charges a "shop charge" as part of the repair bill. This "shop charge" is to help defray the costs of certain materials that cannot be accurately itemized, but which are generally used in the repair and service of vehicles. These items include, but are not limited to, rags, bolts, screws, hand cleaner, small amounts of lubricant, etc. This charge is calculated as a percentage of the total labor charge.

tires are warranted for defects in material or workmanship by the manufacturer.
Please present your receipt and the vehicle to our Service Department during normal business hours.

Replacement parts and

CHOOSING IRA MOTOR GROUP

PLEASE PAY THIS AMOUNT	0.00
SALES TAX	0.00
DISCOUNTS/DEDUCTIBLES	0.00
TOTAL CHARGES	0.00
SHOP CHARGE	0.00
SUBLET AMOUNT	0.00
GAS, OIL, LUBE	0.00
PARTS AMOUNT	0.00
LABOR AMOUNT	0.00
DESCRIPTION	TOTALS

CUSTOMER #: 9272015

1010274

\*INVOICE\*

Toyota Scion

> 161 Andover St. \* Rt. 114 Danvers, MA 01923 978-739-8333 \* 800-230-0982 www.iramotorgroup.com



PAGE 1

BUS:		CET I		CED	VICE ADVICED		ww.mamotorgre		
COLOR	YEAR	CELL: MAKE/MODEL		SEN	VICE ADVISOR:	9530 SC	OTT HERW	IG IN/ OUT	TAG
ABSOLUTELY		OYOTA ECHO	77,		1235Y0097074			/31112	
DEL DATE		TE WARR. EXP.	PROMIS	SED	PO NO.	RATE	PAYMENT	INV. DA	ATE
14NOV00 IS 14NOV00 DI	1		WAIT 1			VARIES	CASH	18AUG	11
		2:28 18AUG		S: STK	C:TY4242 ENG:			9 -	
		TYPE HOURS		D /DVIIAT	JST TYPE NOIS	LIST	NE'	r To	TAL
PARTS: 31112 FOU MANIFOLD	OVISE 5 1.0 F 5287 0.00 JND CEN FLANGE ***	REE DIAGNOS BEAULIEU, ( IDIAG LABOR: TER PIPE AN IS ROTTED	O.00  O.THE MUI  BADLY.	#: / OTHER: FFLER A		TOTAL L ROUGH. T	INE A: HE EXH		/C) .00
CI PE	ERFORM ADVISO INVOIC 5287		NSPECTION ACH TOP CO	OPY OF	ICLE. FORM TO YOUR		0.00	0 0.	.00
	5287 ***TIRE	BEAULIEU, C CT S ARE 5/32* BEAULIEU, C	CHUCK LIC	#: /			0.00	22	.00
PARTS:	0.00	LABOR:	0.00	OTHER:	0.00	TOTAL L	ALGSSSSSSSSSSSSSSSSSSSSSSSSSSSSSSSSSSSS	700	.00
		*****							10.0000007
			*	THANK	YOU FOR CHOO			DANVERS	*

TO SERVICE YOUR VEHICLE

IF YOU ARE NOT 100% SATISFIED

\*\*\* PLEASE CONTACT \*\*\*

CHARLIE ALICARDI, SERVICE DIRECTOR

978-739-8391 calicardi@iramotorgroup.com

OR LORRAINE OBRIEN 978-739-3770

ALL PARTS INSTALLED ARE NEW OR FACTORY REBUILT UNLESS SPECIFIED OTHERWISE

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE BEYOND OUR CONTROL.

In addition to the charges for parts, labor, tax, etc., Ira Toyota Scion also charges a "shop charge" as part of the repair bill. This "shop charge" is to help defray the costs of certain materials that cannot be accurately itemized, but which are generally used in the repair and service of vehicles. These items include, but are not limited to, rags, bolts, screws, hand cleaner, small amounts of lubricant, etc. This charge is calculated as a percentage of the total labor charge.

Replacement parts and tires are warranted for defects in material or workmanship by the manufacturer. Please present your receipt and the vehicle to our Service Department during normal business hours.

DESCRIPTION	TOTALS
LABOR AMOUNT	0.00
PARTS AMOUNT	0.00
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
SHOP CHARGE	0.00
TOTAL CHARGES	0.00
DISCOUNTS/DEDUCTIBLES	0.00
SALES TAX	0.00
PLEASE PAY THIS AMOUNT	0.00



at iraca com

	Quality Vehicle Inspection
Yea 3	r/Model: 00 Cdi) Date: 8-A-// 5 900 97674 Repair Order #: 10/02/14  Technician:
s / Blades Pitting)	CHECKED AND OKAY  MAY NEED FUTURE ATTENTION  REQUIRES IMMEDIATE ATTENTION  BATTERY PERFORMANCE  Battery Terminals / Cables / Mountings  Check Condition of Battery (Storage Capacity Test)  Pass  Recharge Retest  Fail
s /	Brake Lining mm Tire Tread 32nds Wear Pattern Tire Pressure 32 psi  Inspect Brake Lining mm Tire Tread 32nds Wear Pattern Tire Pressure 32 psi  Brake Lining mm Tire Pressure 32 psi  Inspect Tire Wear  Brake Lining mm Tire Tread 32nds Wear Pattern Tire Tread 32nds Wear Pattern Tire Tread 32nds Wear Pattern Tire Pressure 32 psi  Brake Inspection Not Performed This Visit
ank  / Brake	Think Yun

Assistant Service Manager:

CHECKED AND OKAY MAY NEED FUTURE ATTENTION REQUIRES IMMEDIATE ATTENTION INTERIOR/EXTERIOR Head Lights / Tail Lights / Turn Signals / Brake Lights Hazard Warning Lights / Exterior Lamps Windshield Washer Spray / Wiper Operation / Wiper Wiper Arms / Including Rear (if appliable) Windshield Condition (Inspect for Cracks, Chips, or Upholstery / Carpet / Floor Mats / Mirrors / Glass **Emergency Brake Adjustment** Horn Operation Fuel Tank Cap Gasket Air Conditioning Filter (if equipped) Clutch Operation (if equipped) UNDER VEHICLE Shock Absorbers / Suspension Steering Gear Box / Linkage and Boots / Ball Joints / **Dust Covers** Muffler / Exhaust Pipes / Mountings Engine Oil and/or Fluid Leaks Brake Lines / Hoses / Parking Brake Cable Drive Shaft Boots / Constant Velocity Boots / U-joints Transmission Linkage (if equipped) Transmission / Differential / Transfer Case (Check Flu Level, Fluid Condition and Fluid Leaks) Fuel Lines and Connections / Fuel Tank Band / Fuel Ta Vapor Vent System Hoses Inspect Nuts and Bolts on Body Chassis UNDER HOOD Fluid Levels: Oil / Coolant / Battery / Power Steering Fluid / Washer / Automatic Transmission Engine Air Filter Drive Belts (condition and adjustment) Engine Coolant Protection Cooling System Hoses / Heater Hoses / Air Condition Hoses and Connections

Radiator Core / Air Conditioning Condenser (if equipped)

TOYOTA the right people, parts & service -



INVOICE NO.

TOWN FAIR TIRE CENTERS OF MASSACHUSETTS LLC 129-139 ENDICOTT ST., DANVERS, MA 01923 TEL (978) 777-8350

#### INVOICE

40445-566 ACCOUNT NO. P.O. #. PHONE PHONE MR. CURRENT MILEAGE YEAR, MAKE, MODEL 28451 00 TOYOTA Echo 11915 RED G.P. # DATE TIME 366M 02/11/2010 11:27 QTY SIZE DESCRIPTION IBM # LIST PRICE **AMOUNT** FIX FLAT NEW VALVE & BALANCE 00153 14.95 3.95 3.95 1 FLAT REPAIR 00194 14.95 0.00 0.00 Free Flat Repair - The tire is removed from the wheel and thoroughly inspected. If the tire has a puncture wound, it will be repaired from the inside using a combination patch-plug. If the tire is leaking from the bead area, the tire and the rim are thoroughly cleansed and sealed with a bead sealant. Due to the internal flat repair it is recommended to install a new valve stem and balance the tire before it is put back on the vehicle. The normal charge for these items is \$14.95 to \$19.95 depending on the rim diameter. The discounted price for the new valve stem and balancing the tire that has been repaired is only \$3.95. xplanation: RR TIRE SLOW LEAK SUB-TOTAL 3.95 ORQUE: 76 MA SALES TAX PSI--FR:32 RR:32 0.25 SIGNATURE NON-TAXABLE 0.00 TOTAL 4.20 ayaway Deposit alance Due 0.00 4.20

#### SAFETY WARNING

ter installation of mag wheels, all its or bolts must be retorged etightened) after the first 25 miles USTOMER INITIALS

#### **COMMENTS - COMPLIMENTS - COMPLAINTS**

Town Fair serves thousands of customers each year. In order to help us serve you better, if you have a comment, compliment, or complaint or just want to talk to us about our operation - please call - it will be greatly appreciated.

Contact or Write

NEIL MELLEN, PRESIDENT TOWN FAIR TIRE

460 COE AVENUE EAST HAVEN, CT 06512

TELEPHONE (203)467-8600

OR TOLL FREE 1 (800) 972-2245 OR 1 (888) TOWNFAIR

OR VISIT OUR WEBSITE @ www.townfair.com



TOWN FAIR TIRE CENTERS OF MASSACHUSETTS LLC 129-139 ENDICOTT ST., DANVERS, MA 01923 TEL (978) 777-8350

# INVOICE - Layaway Payment

	P.O. #.	1-14		PHON	NE#	
				PHON		
			CURRENT	MILEAGE	YEAR, N	MAKE, MODEL
			<u></u>	0	1/2	,
	015			Y	产品代表	
CLERK #		Y	DATE	Y TIME		
366	I-4 3	02/			file   1997   19	
	CLERK#	366	366 G.P.# 02/	DLERK# G.P.# DATE 366 02/11/2010	CLERK # G.P. # DATE TIME 366 02/11/2010 11:38	CURRENT MILEAGE YEAR, N 0 915 CLERK # G.P. # DATE TIME 366 02/11/2010/11:38

	SUB-TOTAL	0.00
	MA SALES TAX	0.00
SIGNATURE	NON-TAXABLE	0.00
	TOTAL	0.00
ayaway Balance 4.20	IOTAL	

lash 5.00 hange 0.00

#### SAFETY WARNING

fter installation of mag wheels, all uts or bolts must be retorged etightened) after the first 25 miles USTOMER INITIALS

#### **COMMENTS - COMPLIMENTS - COMPLAINTS**

Town Fair serves thousands of customers each year. In order to help us serve you better, if you have a comment, compliment, or complaint or just want to talk to us about our operation - please call - it will be greatly appreciated.

Contact or Write
NEIL MELLEN, PRESIDENT TOWN FAIR TIRE
460 COE AVENUE EAST HAVEN, CT 06512
TELEPHONE (203)467-8600
OR TOLL FREE 1 (800) 972-2245 OR 1 (888) TOWNFAIR
OR VISIT OUR WEBSITE @ www.townfair.com

# Five Star Auto Repair

191 Essex St Beverly, Massachusetts 01915 P (978) 922-9700 F (978) 927-4544

Red Troyoth

Estimate Creation Date: 02/27/2018 08:53

		376LP8	2000 Toyota Echo 1.5L, L4, USA/Canada 376LP8	4, USA/Canada	
	8	Miles			
		Part#/OpCode/Tax Option	Qty/Hrs	Price	ě
Part	Suspension Strut Assembly coil spring bushing & mount left front	4851059396	1.00	\$296.8	Total
Part	Suspension Strut Assembly coil spring bushing & mount right front	485105962	1.00	\$296.66	\$296.66
Labor	removed and replaced front strut assembly		1.00	\$245.00	\$245.00
tery	Battery R&R				\$838.32
Type		Part#/OpCode/Tax Option	Otv/Hrs	6	
Part	Battery installed	00544270635	1.00	\$119.95	Total
Fee	oli cnange & filter state inspection	Non Taxed	1.00	\$29.95 \$29.95 \$35.00	\$29.95

12 month wraranty on parts and labor if deffective only

\$35.00

\$1028.22 \$46.45 \$1074.67

\$3.80

Parts Total: Labor Total: Shop Supplies: Hazardous Materials:

Fees: Subtotal: Sales Tax:

Total:

\$743.22 \$245.00

signature:

date: / /



Meineke Car Care Center #398

119 Rantoul Street Beverly, MA 01915 (978)921-1577 Invoice Number: 18582

Invoice Date: 10-17-11 Estimate ID: 036405

Invoice Code: 764109N763448S45

"Each Shop Individually Owned and Operated"

www.meineke.com

repairs for Echo

Menicie Odometer Tag

2000 TOYOTA ECHO

Odometer 31,395 <u>Tag</u> MA 376LP8

Vin

Tech EQ1 Writer Ad Lead
\*\*\* REPEAT

Quantity Item	Description	Marcantu	100	AD A/D	11.77.0	
ALIGN&TIRE	The Committee of the Co	Warranty	IVIA	AP A/D	Unit Price	Total
2.00 2700-74185 1.00 LABOR	SWAY BAR LINK/KIT SHOP LABOR TO INSTALL SWAY BAR LINKS		A A	A A	21.00 90.00	42.00 90.00
VIS&SAFETY					Job Total:	132.00
1.00 ST1	MASS STATE INSPECTION		Α	Α	29.00 Job Total:	29.00 <b>29.00</b>

enstalled front on Car

hris, Paul and the staff at Meineke Beverly want to thank you for your patronage. Your satisfaction is very important to us.

ales Tax 1: 2.78

lap Code Legend

=Sugg-Failure Likely =Sugg-Customer Req. A/D Legend

A=Accepted

D=Declined

Visa

=Sugg-Maintenance =Sugg-Recommendation =Req-Performance

=Req-Performance =Req-Design Spec =Req-Missing PAYMENT RECEIPT

166.30

Shop Supplies:
Total Parts:
Total Labor:
Sub Total:

Sales Tax:

**Total Due:** 

2.78 **\$166.30** 

2.52

71.00

90.00

163.52

Printed: 10/17/2011 at 10:00:29AM

3Y X \_

112840

## WINDHAM MOBIL SERVICE STATION

18 MAMMOTH RD.

Windham, NH 03087-0000 Shop Phone: (603) 594-2410 Fax: 594-2430

Email: WINDMOBIL@COMCAST.NET Web Address: WWW.WINDHAMMOBIL.COM Invoice

38156

Estimate Ref #39,678 Date Printed: 10/04/2016

Printed Time: 12:09 pm

Hat/Ref:

MANUTE BIOLIS

WINDHAM MOBIL SERVICE CENTER

Time Promised:

ECHO L4 1.5L 1497CC FI GAS N 1NZFE 35Y0097074

Mileage In: 39,058

Date Written:

09/30/2016

Mileage Out: 39,058

Written By:

Save Old Parts: No

Job Name	Description			ora r arts. NO	
	Description	Technician	Qty	List	Esstaval 1
EVAP.TEST	SMOKE EHEL TANK AND WAR		acy	LIST	Extended
Labor 1	SMOKE FUEL TANK AND HOSES  Work Requested - CHECK EVAP.SYST  LOCATE LEAK	carl EM TO	1.50	95.00	142.50
Work Performed - SMOKE	SERVICE PORT AND ACTIVATE SOLENOID.				. 12.00
REPLACE CANISTER PUR AND FILLER TUBE	RGE ASSEMBLY				
Part 77201-52060	PIPE				
Part 77300-20010	CAP		1.00	155.27	155.27
Part 77740-52030			1.00	29.56	29.56
	CANISTER ASSEMBLY		1.00	380.42	380.42

Job #1 Note/Title

**NEEDS** 

FILLER TUBE ASSEMBLY

CHARCOAL CANISTER W/ VSV SOLENOID

# "WE APPRECIATE ALL Y



carl

Payment Date	Туре	Method	Amount
10/4/2016	Credit	MasterCard Payment Totals:	707.75 <b>\$707.75</b>

Parts:	\$565.25
Labor:	\$142.50
Sublet:	\$0.00
Misc:	\$0.00
Hazmat:	\$0.00
Supplies:	\$0.00

Tax Total: \$0.00 Invoice Total: \$707.75 Less Paid: 707.75 **Balance Due:** \$0.00



#### Weineke Car Care Center #398

119 Rantoul Street Beverly, MA 01915 (978)921-1577

Invoice Number: 17894

Invoice Date: 08-19-11 Estimate ID: 034845

Invoice Code: 763874U763750H4

"Each Shop Individually Owned and Operated"

000 TOYOTA ECHO

<u>Odometer</u> 31,125

Vin

Writer Tech Ad Lead EQ1 REPEAT

Quantity Item	Description					
EXHAUST	2 comption	Warranty	M	AP A/D	Unit Price	Total
1.00 IC5738 1.00 MUFFLER LABO 2.00 MISCPART 1.00 1 P	MUFFLER MUFFLER LABOR J HOOK PIPE	1 Year	A A A	A A A	266.56 82.50 8.99 18.00 Job Total:	266.56 82.50 17.98 18.00 385.04



thris, Paul and the staff at Meineke Beverly want to thank you for your patronage. Your satisfaction is very important to us.

ales Tax 1: 19.84

A/D Legend

A=Accepted

Map Code Legend

1=Sugg-Failure Likely 2=Sugg-Customer Req. 3=Sugg-Maintenance

4=Sugg-Recommendation A=Req-Performance

3=Req-Design Spec C=Req-Missing

PAYMENT RECEIPT

Visa 419.83 Shop Supplies: 14.95 **Total Parts:** 302.54 **Total Labor:** 82.50 Sub Total: 399.99 Sales Tax: 19.84 **Total Due:** \$419.83

Printed: 8/19/2011 at 10:29:45AM

#### massuui CERTIFICATE OF REGISTRATION RMV Division M.G.L. Chapter 90 Section 24B makes it a crime to alter this Certificate EFFECTIVE DATE EXPIRES PAN PASSENGER 09/01/15 LAST DAY OF 08 17 92522200016022 IFRS MODEL YEAR MODEL BODY STYLE/TYPE COLOR TOTAL REGISTERED WEIGHT FOR A VEHICLE Not valid without official 2000 CARRYING TOYT **ECHO** SEDAN RED PASSENGERS FOR HIRE: MAXIMUM signature of Registrar COMMERCIAL VEHICLE OR TRAILER. EHICLE IDENTIFICATION NUMBER TITLE NUMBER JTDBT1235Y0097074 NUMBER OF LIBERTY MUTUAL INS AV332837 PASSENGERS THAT CAN BE Cru C. Swiny ESIDENTIAL ADDRESS (IF DIFFERENT) SEATED AME(S) OF OWNER(S) AND MAILING ADDRESS 60.00 REGISTRATION 005533 0.00 TITLE 0.00 SPECIAL PLATES 0.00 SALES TAX TOTAL 60.00 MASSACHUSETTS DEPARTMENT OF TRANSPORTATION REGISTRY OF MOTOR VEHICLES DIVISION The records of the RMV database constitute the official status of the vehicle registration,

Important Information for Vehicle Owners

CHANGE OF ADDRESS

STREET ADDRESS

Every person operating a motor vehicle shall have the Certificate of Registration for the motor vehicle and for the trailer, if any, and his/her license to operate, upon his/her person or in the vehicle, in some easily accessible place.

DAYS OF REGISTRATION.

IF THIS VEHICLE IS NEWLY ACQUIRED, IT MUST BE INSPECTED WITHIN SEVEN (7)

- By law, you must report any change of address to the RMV within 30 days in writing. Address changes can be made on the RMV website: www.massrmv.com or by mail to: RMV, P.O. Box 55889, Boston, MA 02205-5889. Once you have reported the address change to the RMV, please write corrected address in box provided above.
- Return the registration plates to the RMV immediately if:
- The vehicle has been sold or junked and the registration is not going to be transferred to another vehicle. Keep a copy of the Bill of Sale, Title, and completed Reassignment of Title for your records to document the transfer.
- You move to another state and you register the vehicle in that state.



 The insurance policy is not renewed or is cancelled and there is no plan to obtain a new policy.

Transferring Your Plates: Massachusetts law (M.G.L. Chapter 90, Section 2) allows you to transfer valid registration plates from this vehicle to a newly acquired new or used motor vehicle or trailer while you obtain insurance and a new registration. All the following must be met: 1. You are at least 18 years of age and you own the motor vehicle or trailer identified on this Registration Certificate. 2. You transfer ownership of this vehicle to another person or permanently lose possession of it (such as through repossession, etc.); 3. The newly acquired vehicle is of the same vehicle type (passenger vehicle to passenger vehicle, trailer to trailer etc.); the same registration type (passenger to passenger, commercial to commercial); and has the same number of wheels; and, 4. The seller and buyer properly complete the Assignment of the Certificate of Title (for the newly acquired "used" vehicle) or Certificate of Origin (if a "new" vehicle). If all the above are met, you may operate the newly acquired vehicle with the transferred plates up to 5:00 pm of the 7th calendar day following the date of transfer (or loss of possession). The day of transfer or loss is day #1. During that 7 days, you must carry the Bill of Sale (or the dealer's Purchase Contract) for the newly acquired vehicle and this Registration Certificate when operating the vehicle. See FAQs About the Seven-Day Registration Transfer Law on the RMV's website at www.massrmv.com.

No Insurance Card Required: Massachusetts's law does <u>not</u> require an Insurance card. The law, M.G.L. Chapter 90, Section 34A and Chapter 175, Section 113A requires the vehicle's owner to maintain a compulsory motor vehicle insurance policy or bond for bodily injury coverage and property damage insurance. If an insurer is identified on the face of this *Registration Certificate*, it is required by law to electronically notify the RMV (Registry of Motor Vehicles) if coverage lapses. The vehicle owner is then notified by the RMV to obtain new insurance within 10 days or the registration will be revoked. Bonds are filed with the State Treasurer's Office.

#### BE FIRST IN LINE BY GOING ONLINE AT WWW.MASSRMV.COM

Schedule a Road Test

SPECIAL MESSAGE

Renew Your Driver's License

Renew Your Registration

Pay Citations/Court Hearing Fee

Replace Your Driver's License

Request a Duplicate Title

Request a Duplicate Registration

Change Your Address

Cancel My Plate/Registration

Order a Special Plate

**NEED TO VISIT AN RMV OFFICE?** 

SAVE TIME Complete Your Application Online!



Hogan keeps you rolling!

**SINCE 1915** 

Woburn 781-933-4000 Westwood

781-329-9090 Waltham 781-891-7350 Natick 508-655-6700

Sales

Person 578

Purchase

Ord. No.

stomer Authorization for Total

Beverly 978-927-4065

■ Lowell 978-458-6600 Hudson 978-568-0404

www.hogantire.com

Other Phone

**CASH SALE** 

Invoice Date	Cust Na			The state of the s
	Cust No.	Order No.	Page	Invoice No.
05/04/2016	7	7 - 895803	1/1	850590

Visa 45.00 (EcHo)

License: 376LP8 Mileage: 38,447

2000 TOYOTA ECHO

Time in 1:09 PM Time out 1:20 PM

old

Main Phone

Ship To:

0.7	
Ship Via	Terms: RET
	VIN: JTDBT1235Y0097074

em No.	Description	Qty	Qty	F.E.T.	Price	N
AG	DIAG/INSPECTION SERVICES	Ordered	Shipped		Frice	Net Extension
CANAO	DIAGNOSTIC CHK ENG LIGHT SCAN/RESET	1.00	1.00		0.00 45.00	0.00 45.00
1 288	*P0440 SM EVAP LEAK, CLEARED				40.00	45.00

SA Method			Signature	
SA	****2624	45.00	PMC	
		100	7.116	

recommend you return for a torque check after the first 10-50 miles when wheels are removed. See hogantire.com for warranty details. porate Office: PO Box 2235, Woburn, Ma 01888 | 781-933-4004

Sub-Total Labor:

Entered: 578

45.00

Non-Taxable Amount:

45.00

Taxable Amount:

0.00

45.00

Total:

#### WINDHAM MOBIL BRAKE AND TIRE

54 HAVERHILL RD

Windham, NH 03087-0000 Shop Phone: (603) 818-8430 Fax: (603) 216-5193

Email: WINDMOBIL@COMCAST.NET Web Address: WWW.WINDHAMMOBIL.COM Invoice

34963 Estimate Ref #36,520

Date Printed: 01/08/2015 Printed Time: 4:31 pm

Hat/Ref:

WINDHAM MOBIL SERVICE CENTER

Time Promised:

2000 TOYOTA ECHO L4 1.5L 1497CC FI GAS N 1NZFE VII Lice Unit

Mileage In: 36,541

Date Written:

01/07/2015

Mileage Out: 36,580

Written By:

Save Old Parts: No.

Job Name	Description	Technician	Qty	List	Extended
lob #1	REPLACE EXHAUST BOLT AND SPRING	ВОВ	4.,	List	Extended
Part 4978 Part 4979 Part 9215 abor 1	EXHAUST BOLT EXHAUST SPRING GASKET Work Requested - REPLACE EXHAUS SPRING ACT ROTTED BOLTS FROM MANIFOLD	ST BOLT AND	2.00 2.00 1.00 1.50	8.94 10.14 12.38 84.50	17.88 20.28 12.38 126.75

Job #2	ENGINE MOUNT - Replace - Rear BOB			
Part 1237123011	Mount ENGINE MOUNT - Rear Mount - Auto Trans Work Requested - ENGINE MOUNT - Replace - Rear Mount	1.00	64.42	64.42
Labor 1		0.80	84.50	67.60

# "WE APPRECIATE ALL YOUR BUSINESS"

Payment Date	Туре	Method	Amount
1/8/2015	Check	#7252 Payment Totals:	341.91 \$341.91

Parts: \$114.96 Labor: \$194.35 Sublet: \$0.00 Misc: \$0.00 Hazmat: \$14.86 Supplies: \$17.74

Tax Total:

\$0.00 \$341.91

Invoice Total: Less Paid:

341.91 \$0.00

**Balance Due:** 

665060

\*INVOICE\*

PAGE 1

ra Toyota
Scion

161 Andover St. \* Rt. 114 Danvers, MA 01923 978-739-8333 \* 800-230-0982 www.iramotorgroup.com

SERVICE ADVISOR: 6441 ILANA SNYDERMAN MILEAGE IN/ OUT TAG ABSOLUTELY 00 TOYOTA ECHO JTDBT1235Y0097074 18512/18512 268. PROD. DATE DEL DATE WARR. EXP. PROMISED PO NO. AYMENT INV. DATE 14NOV00 IS 85.00 CASH 24NOV06 **OPTIONS:** STK:TY4242 ENG:1NZ-FF 08:36 24NOV06 09:17 24NOV06 LINE OPCODE TECH TYPE HOURS LIST NET TOTAL A STATE INSPECTION SI STATE INSPECTION 925 RODRIGUEZ, TROY LIC#: / CT 29.00 29.00 \*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\* !!!!!!!!!!THANK YOU!!!!!!!!!!!!!!!!!!!!!!!!!!!!!!! FOR CHOOSING IRA MOTOR GROUP 





ALL PARTS INSTALLED ARE NEW OR FACTORY REBUILT UNLESS SPECIFIED OTHERWISE

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE BEYOND OUR CONTROL.

In addition to the charges for parts, labor, tax, etc., Ira Toyota Scion also charges a "shop charge" as part of the repair bill. This "shop charge" is to help defray the costs of certain materials that cannot be accurately itemized, but which are generally used in the repair and service of vehicles. These items include, but are not limited to, rags, bolts, screws, hand cleaner, small amounts of lubricant, etc. This charge is calculated as a percentage of the total labor charge.

x\_\_\_\_\_

Replacement parts and tires are warranted for defects in material or workmanship by the manufacturer.

Please present your receipt and the vehicle to our Service Department during normal business hours.

SALES TAX PLEASE PAY	0.00
DISCOUNTS/DEDUCTIBLES	0.00
TOTAL CHARGES	29.00
SHOP CHARGE	0.00
SUBLET AMOUNT	0.00
GAS, OIL, LUBE	0.00
PARTS AMOUNT	0.00
LABOR AMOUNT	29.00
DESCRIPTION	TOTALS

**Toyota** 9272015 618379 \*INVOICE\* 161 Andover St. \* Rt. 114 Danvers, MA 01923 978-739-8333 \* 800-230-0982 PAGE 1 www.iramotorgroup.com SERVICE ADVISOR: 6757 HOGAN COLOR YEAR MAKE/MODEL VIN MILEAGE IN/ OUT TAG ABSOLUTELY TOYOTA ECHO 00 JTDBT1235Y0097074 17703/17703 T272 **DEL DATE** PROD. DAJE WARR. EXP. **PROMISED** PO NO. **PAYMENT** INV. DATE 14NOV00 IS 17APR06 85.00 CASH 17APR06 OPTIONS: STK:TY4242 ENG:1NZ-FF 08:35 17APR06 10:46 17APR06 LINE OPCODE TECH TYPE HOURS LIST NET TOTAL INSPECT DRIVERS FLOOR PANEL FOR SURFACE RUST, DETERMINE IF FURTHER WORK IS REQUIRED. LOC/4620MF CAUSE: RECALL 4620MA INSPECT FLOOR PAN AND APPLY SEALER KIT 6756 RAPENELLI, SERGIO LIC#: / WT45 (N/C)1 04004-67152 FLOOR SILENCER KIT (N/C)5 C0505-MS930-DS TEROSTAT SEALER MS-9 (N/C)FC: RECALL PART#: COUNT: CLAIM TYPE: AUTH CODE: C/R RECALL TECH VERIFIED RECALL TECH PERFORMED RECALL \*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\* 3 COURTESY INSPECTION CI COURTESY INSPECTION 6756 RAPENELLI, SERGIO LIC#: / (N/C)\*\*\*\*\*\*\* FOR CHOOSING IRA MOTOR GROUP 

ALL PARTS INSTALLED ARE NEW OR FACTORY REBUILT UNLESS SPECIFIED OTHERWISE

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE BEYOND OUR CONTROL.

In addition to the charges for parts, labor, tax, etc., Ira Toyota Scion also charges a "shop charge" as part of the repair bill. This "shop charge" is to help defray the costs of certain materials that cannot be accurately itemized, but which are generally used in the repair and service of vehicles. These items include, but are not limited to, rags, bolts, screws, hand cleaner, small amounts of lubricant, etc. This charge is calculated as a percentage of the total labor charge.

x\_\_\_\_\_

Replacement parts and tires are warranted for defects in material or workmanship by the manufacturer. Please present your

Please present your receipt and the vehicle to our Service Department during normal business hours.

PLEASE PAY THIS AMOUNT	0 00
SALES TAX	0.00
DISCOUNTS/DEDUCTIBLES	0.00
TOTAL CHARGES	0.00
SHOP CHARGE	0.00
SUBLET AMOUNT	0.00
GAS, OIL, LUBE	0.00
PARTS AMOUNT	0.00
LABOR AMOUNT	0.00
DESCRIPTION	TOTALS

Ta Toyota CUSTOMER #: 9272015 1010274 Scion \*INVOICE\* 161 Andover St. \* Rt. 114 Danvers, MA 01923 978-739-8333 \* 800-230-0982 PAGE 1 www.iramotorgroup.com 2015 SERVICE ADVISOR: 9530 SCOTT HERWIG COLOR YEAR MAKE/MODEL VIN MILEAGE IN/ OUT TAG ABSOLUTELY 00 TOYOTA ECHO JTDBT1235Y0097074 31112/31112 T704 **DEL DATE** PROD. DATE WARR, EXP. PROMISED PO NO. RATE **PAYMENT** INV. DATE 14NOV00 IS 4NOV00 WAIT 18AUG11 VARIES CASH 18AUG11 **OPTIONS:** STK: TY4242 ENG: 1NZ-FF 09:53 18AUG11 112:28 18AUG11 LINE OPCODE TECH TYPE HOURS LIST NET TOTAL CUST STATES THERE IS A LOUD ENGINE/EXHAUST TYPE NOISE, PLEASE CK AND ADVISE FDIAG 1.0 FREE DIAGNOSIS 5287 BEAULIEU, CHUCK LIC#: / IDIAG (N/C)PARTS: LABOR: 0.00 0.00 OTHER: 0.00 TOTAL LINE A: 0.00 31112 FOUND CENTER PIPE AND THE MUFFLER ARE ROTTED THROUGH. THE EXH MANIFOLD FLANGE IS ROTTED BADLY. PERFORM 26-POINT INSPECTION OF VEHICLE. ADVISOR WILL ATTACH TOP COPY OF FORM TO YOUR INVOICE. CI PERFORM 26-POINT INSPECTION OF VEHICLE. ADVISOR WILL ATTACH TOP COPY OF FORM TO YOUR INVOICE. 5287 BEAULIEU, CHUCK LIC#: / CT 0.00 0.00 BR3 REARS ARE 3MM, FRONTS ARE 4MM 5287 BEAULIEU, CHUCK LIC#: CT 0.00 0.00 TR5 \*\*\*TIRES ARE 5/32\*\*\* 5287 BEAULIEU, CHUCK LIC#: / CT 0.00 0.00 PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE B: 0.00 \*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\* THANK YOU FOR CHOOSING IRA TOYOTA DANVERS \* TO SERVICE YOUR VEHICLE YOU ARE NOT 100% SATISFIED \*\*\* PLEASE CONTACT CHARLIE ALICARDI, SERVICE DIRECTOR calicardi@iramotorgroup.com 978-739-8391 OR LORRAINE ALL PARTS INSTALLED ARE NEW OR FACTORY REBUILT UNLESS SPECIFIED OTHERWISE Replacement parts a tires are warranted Tor NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR PARTS AMOUNT 0.00 ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE BEYOND OUR CONTROL. defects in material or GAS, OIL, LUBE 0.00 workmanship by the In addition to the charges for parts, labor, tax, etc., Ira Toyota Scion also charges a "shop charge" as part of the repair bill. This "shop charge" is to help defray the costs of SUBLET AMOUNT 0.00 manufacturer. SHOP CHARGE certain materials that cannot be accurately itemized, but which are generally used in the repair and service of vehicles. These items include, but are not limited to, rags, bolts, 0.00 Please present your TOTAL CHARGES 0.00 screws, hand cleaner, small amounts of lubricant, etc. This charge is calculated as a percentage of the total labor charge. receipt and the vehicle DISCOUNTS/DEDUCTIBLES 0.00

to our Service

Department during

normal business hours.

SALES TAX

PLEASE PAY THIS AMOUNT 0.00

0.00



Meineke Car Care Center #398

119 Rantoul Street Beverly, MA 01915 (978)921-1577 Invoice Number: 18582

Invoice Date: 10-17-11 Estimate ID: 036405

Invoice Code: 764109N763448S45

"Each Shop Individually Owned and Operated"

SOLD TO:

Www.meineke.com

repairs for Echo

Vin

Tech Writer Ad Lead EQ1 \*\*\* REPEAT

Quantity Item	Description	Marsanti	MAD A/D		
ALIGN&TIRE	The State of the S	Warranty	MAP A/D	Unit Price	Total
2.00 2700-74185 1.00 LABOR	SWAY BAR LINK/KIT SHOP LABOR TO INSTALL SWAY BAR LINKS		A A A A	21.00 90.00	42.00 90.00
VIS&SAFETY				Job Total:	132.00
1.00 ST1	MASS STATE INSPECTION		A A	Job Total:	29.00 <b>29.00</b>

enstalled front on Car

hris, Paul and the staff at Meineke Beverly want to thank you for your patronage. Your satisfaction is very important to us.

ales Tax 1: 2.78

lap Code Legend

=Sugg-Failure Likely =Sugg-Customer Req. =Sugg-Maintenance

=Sugg-Maintenance =Sugg-Recommendation =Reg-Performance

=Req-Performance =Req-Design Spec =Req-Missing Visa

A/D Legend

A=Accepted

D=Declined

PAYMENT RECEIPT

166.30

 Shop Supplies:
 2.52

 Total Parts:
 71.00

 Total Labor:
 90.00

 Sub Total:
 163.52

 Sales Tax:
 2.78

 Total Due:
 \$166.30

Printed: 10/17/2011 at 10:00:29AM

112840



TOWN FAIR TIRE CENTERS OF MASSACHUSETTS LLC 129-139 ENDICOTT ST., DANVERS, MA 01923 TEL (978) 777-8350

# INVOICE - Layaway Payment

INVOICE NO. 40445-566					- aymen		74
ACCOUNT NO.	P.O. #.			1	24		
MF ME AC				CURRENT	MILEAGE T	YEAR, N	MAKE, MODEL
SALE TYPE	Y CLERK#	G.P. #		DATE	) TIME		
9 Layaway Payment QTY SIZE Y DE	366 ESCRIPTION		02/	11/2010	)11:38 IST	PRICE	AMOUNT

	SUB-TOTAL	0.00
	MA SALES TAX	0.00
SIGNATURE	NON-TAXABLE	0.00
	TOTAL	0.00

lash 5.00 hange 0.00 lew Balance 0.00

#### SAFETY WARNING

fter installation of mag wheels, all uts or bolts must be retorged etightened) after the first 25 miles SUSTOMER INITIALS

#### **COMMENTS - COMPLIMENTS - COMPLAINTS**

Town Fair serves thousands of customers each year. In order to help us serve you better, if you have a comment, compliment, or complaint or just want to talk to us about our operation - please call - it will be greatly appreciated.

Contact or Write
NEIL MELLEN, PRESIDENT TOWN FAIR TIRE
460 COE AVENUE EAST HAVEN, CT 06512
TELEPHONE (203)467-8600
OR TOLL FREE 1 (800) 972-2245 OR 1 (888) TOWNFAIR
OR VISIT OUR WEBSITE @ www.townfair.com

# Five Star Auto Repair

Beverly, Massachusetts 01915 P (978) 922-9700 F (978) 927-4544 191 Essex St

Red Trayoth

Estimate Creation Date: 02/27/2018 08:53

	× ×	2000 Tc 376LP8	2000 Toyota Echo 1.5L, L4, USA/Canada 376LP8	SA/Canada	
		Miles			
ont s	front spring broken				
lype	Type Description	Part#/OpCode/Tax Option	Qty/Hrs	Price	Total
Zaz	Suspension Strut Assembly coll spring bushing & mount left front	4851059396	1.00	\$296.66	\$296 66
Part	Suspension Strut Assembly coil spring bushing & mount right front	485105962	1.00	\$296.66	\$296.65
Labor	removed and replaced front strut assembly		1.00	\$245.00	\$245.00
atten	Battery R&R				\$838,32
ype	Type Description	Part#/OpCode/Tax Option	Otv/Hrs	G G	
Part	Battery installed oil change & filter	00544270635	1.00	\$119.95 \$29.95	\$119.95 \$20 05
ree	state inspection	Non Taxed	1.00	\$35.00	\$35.00

12 month wraranty on parts and labor if deffective only

signature:

date:

pd.in feeled 2/28/18 CK# 7929

\$35.00

\$1028.22 \$46.45 \$1074.67

\$3.80 \$1.20

Hazardous Materials: Shop Supplies: Labor Total: Parts Total:

Fees:

Sales Tax: Subtotal:

Total:

\$743.22 \$245.00



INVOICE NO.

TOWN FAIR TIRE CENTERS OF MASSACHUSETTS LLC 129-139 ENDICOTT ST., DANVERS, MA 01923 TEL (978) 777-8350

#### INVOICE

MR.							
MRS. MS.				CURRE	NT MILEAGE	The second secon	AKE, MODEL
DDRES					28451	00 TOYO	TA Echo
ITY ST						D.	
SALE TYPE	) CLI	ERK# G.P. #	#	DATE	TIME	RE	<u>SD</u>
)1	36	56M			1011:27		
QTY SIZE	DESCRIPTION	V view and the second	IBM #		LIST	PRICE	AMOUNT
1 FIX FLAT	NEW VALVE & E FLAT REPAIR	BALANCE	0015		14.95 14.95	3.95	3.95
using a combinate cire and the rime and balance the	are choroughi	y creansed	and se	aled	with a	bead seal	ant.
these items discounted poeen repaired is	is \$14.95 to \$ rice for the n only \$3.95.	19 95 deper	ck on t	he ve	hicle.	The norma	l charge
these items the discounted peen repaired is	is \$14.95 to \$ rice for the n only \$3.95.	19 95 deper	ck on t	he ve	nicle. rim di ncing t	The norma	l charge
these items discounted poeen repaired is planation: RR TORQUE: 76	is \$14.95 to \$ rice for the n only \$3.95.	19.95 deper ew valve st	tem and	he ve	rim di ncing t	The norma ameter. he tire t	l charge hat has
End balance the for these items The discounted poeen repaired is Explanation: RR TORQUE: 76	is \$14.95 to \$ rice for the n only \$3.95.	19 95 deper	tem and	he ve	nicle. rim di ncing t	The normal ameter. he tire to the second sec	l charge

#### SAFETY WARNING

fter installation of mag wheels, all uts or bolts must be retorged etightened) after the first 25 miles SUSTOMER INITIALS

#### COMMENTS - COMPLIMENTS - COMPLAINTS

Town Fair serves thousands of customers each year. In order to help us serve you better, if you have a comment, compliment, or complaint or just want to talk to us about our operation - please call - it will be greatly appreciated.

Contact or Write

NEIL MELLEN, PRESIDENT TOWN FAIR TIRE

460 COE AVENUE EAST HAVEN, CT 06512

TELEPHONE (203)467-8600

OR TOLL FREE 1 (800) 972-2245 OR 1 (888) TOWNFAIR

OR VISIT OUR WEBSITE @ www.townfair.com

Du Cu	Year/Mode	1: 00 Colo Date: 8-11
Mileage:	31,110 VIN: JT DBT 123540	70 97674 Repair Order #: 1010214
	SIBLAN	
		ēchnician:
	ED AND OKAY AY NEED FUTURE ATTENTION	CHECKED AND OKAY  MAY NEED FUTURE ATTENTION
	REQUIRES IMMEDIATE ATTENTION	REQUIRES IMMEDIATE ATTENTION
	INTERIOR/EXTERIOR	BATTERY PERFORMANCE
1	Head Lights / Tail Lights / Turn Signals / Brake Lights / Hazard Warning Lights / Exterior Lamps	Battery Terminals / Cables / Mountings
	Windshield Washer Spray / Wiper Operation / Wiper Blades Wiper Arms / Including Rear (if appliable)	Check Condition of Battery (Storage Capacity Test)
1	Windshield Condition (Inspect for Cracks, Chips, or Pitting)	Pass Recharge Retest Fail
	Upholstery / Carpet / Floor Mats / Mirrors / Glass	BRAKE AND TIRE
	Emergency Brake Adjustment	Left Front Right Front
	Horn Operation	Brake Lining mm  Brake Lining mm  Tire Tread 32nds  Tread 32nds
	Fuel Tank Cap Gasket	Wear Pattern  Wear Pattern  Wear Pattern  Tire Pressure 32 psi
	Air Conditioning Fifter (if equipped)	
	Clutch Operation (if equipped)	nspect Brake Lining Inspect Tire Wear
	UNDER VEHICLE	
	Shock Absorbers / Suspension	
	Steering Gear Box / Linkage and Boots / Ball Joints / Dust Covers	
	Muffler / Exhaust Pipes / Mountings	eft Rear Right Rear
	Engine Oil and/or Fluid Leaks	Brake Lining mm
	Brake Lines / Hoses / Parking Brake Cable	Wear Pattern Wear Pattern
	Drive Shaft Boots / Constant Velocity Boots / U-joints / Transmission Linkage (if equipped)	Brake Inspection Not Performed This Visit
	Transmission / Differential / Transfer Case (Check Fluid Level, Fluid Condition and Fluid Leaks)	COMMENTS
	Fuel Lines and Connections / Fuel Tank Band / Fuel Tank Vapor Vent System Hoses	- CHINELETTO
	Inspect Nuts and Bolts on Body Chassis	
	UNDER HOOD	
- Marine	Fluid Levels: Oil / Coolant / Battery / Power Steering / Brake Fluid / Washer / Automatic Transmission	
	Engine Air Filter	Muck Jun
1	Drive Belts (condition and adjustment)	(De C
	Engine Coolant Protection	Cerum
	Cooling System Hoses / Heater Hoses / Air Conditioning	

**Hoses and Connections** 

Radiator Core / Air Conditioning Condenser (if equipped)

TOYOTA the right people, parts & service -

380.42

29.56

155.27

145.50

Extended

00.0\$

**27.707** 

00.0\$

00.0\$

**GT.707**\$

Balance Due:

Invoice Total:

Less Paid:

Tax Total:

Supplies:

Invoice

Date Printed: 10/04/2016 Estimate Ref #39,678 38156

Printed Time: 12:09 pm

380.42

155.27

99.62

### WINDHAM MOBIL SERVICE STATION

18 MAMMOTH RD.

Shop Phone: (603) 594-2410 Windham, NH 03087-0000

Web Address: WWW.WINDHAMMOBIL.COM Email: WINDMOBIL@COMCAST.NET Fax: 594-2430

Time Promised:

WINDHAM MOBIL SERVICE CENTER

2000 TOYOTA ECHO L4 1.5L 1497CC FI GAS N 1NZFE

Mileage Out: 39,058 09/30/2016 Date Written: Mileage In: 39,058 VIN: JTDBT1235Y0097074

Written By:

Save Old Parts: No :MOG

1.00

00.1

00.1

Qty

00.36 1.50 Work Reduested - CHECK EVAP.SYSTEM TO cstl SMOKE FUEL TANK AND HOSES JSIJ

Technician

csrl

LOCATE LEAK Labor 1

Work Performed - SMOKE SERVICE PORT AND ACTIVATE SOLENOID.

Description

CAP 77300-20010 Part PIPE 77201-52060 Part AND FILLER TUBE REPLACE CANISTER PURGE ASSEMBLY

CANISTER ASSEMBLY 77740-52030 Part

FILLER TUBE ASSEMBLY NEEDS **Note/Title** 

CHARCOAL CANISTER WI VSV SOLENOID

Credit

Type

10/4/2016

L# dol

TS3T.9AV3

Job Name

Hat/Ref:

Payment Date

00.0\$ Hazmat: **GT.707**\$ 00.0\$ Misc: Payment Totals: 00.0\$ **97.707** :Jaidu2 MasterCard Method "WE APPRECIATE ALL Y

#### weineke Car Care Center #398

119 Rantoul Street Beverly, MA 01915 (978)921-1577

Invoice Number: 17894

Invoice Date: 08-19-11 Estimate ID: 034845

Invoice Code: 763874U763750H4

SOLD To meineke.com

"Each Shop Individually Owned and Operated"

000 ТОҮОТА ЕСНО

**Odometer** 31,125

Tag MA 376LP8

Vin

Tech EQ1

Writer

Ad Lead DEDEAT

Quantity Item	Description	200			Q1	KEPEAI	
EXHAUST	Description	Warranty	M	AP A/D	Unit Price		Total
1.00 IC5738 1.00 MUFFLER LABO 2.00 MISCPART 1.00 1 P	MUFFLER MUFFLER LABOR J HOOK PIPE	1 Year	A A A	A A A	266.56 82.50 8.99 18.00		266.56 82.50 17.98 18.00
					Job To	tal:	385.04

DATE: 08/19/2011 TIME: 10:30:06 METNEKE 398 119 RANTOUL ST BEVERLY. MA 01915 (978)921-1577 680398 - 1662 SHIFTH 1



hris, Paul and the staff at Meineke Beverly want to thank you for your patronage. Your satisfaction is very important to us.

ales Tax 1: 19.84

ap Code Legend

A/D Legend A=Accepted

Visa

Sugg-Failure Likely Sugg-Customer Req. D=Declined :Sugg-Maintenance

:Sugg-Recommendation =Req-Performance =Req-Design Spec Req-Missing

PAYMENT RECEIPT

419.83

**Shop Supplies: Total Parts:** Total Labor: Sub Total: Sales Tax:

19.84

14.95

302.54

82.50

399.99

**Total Due:** \$419.83 Printed: 8/19/2011 at 10:29:45AM

# Massachusens Department of transportation Registry of Motor Vehicles

### CERTIFICATE OF REGISTRATION

M.G.I. Chanter 90 Section 24B, makes it a crime to alter this Certificat

**RMV Division** 

PAN	-	TRATION TYPE	SSENGER	09/01/15		EXPIRES LAST DAY OF	<b>→</b>	момтн 08	YEAR	92522200016022		
MFRS MODEL YE	TOYT	ЕСНО	BODY STYLE/TYPE SEDAN	COLOR	RE	D .		lid withou ture of R			IF VEHICLE CARRYING PASSENGERS FOR HIRE:	TOTAL REGISTERED WEIGHT FOR A COMMERCIAL VEHICLE OR TRAILER.
JTDBT1	10N NUMBER 235Y009707		ECOMPANY BERTY MUTU		TITLE NUM	MBER 1332837	1	Cu C. Dwiny			MAXIMUM NUMBER OF PASSENGERS THAT CAN BE	
RESIDENTIAL ADD	RESS (IF DIFFERENT)						Cu	υ C.	DWI	ny	SEATED.	
NAM	MASS	ACHUSE	TTS DEPART	MENT OF TR	H23	BPORTATIO	FEES	TITLE SPECIA SALES	TRATION AL PLATES TAX TOTAL		0	0.00
		REGIST	RY OF MOTOF database constitute	R VEHICLES	DIV	ISION						
SPECIAL MESSAGE	MUST BE IN	SPECTED	S NEWLY ACQUE			HANGE OF ADDRESS		7.				8
	DAYS OF RE	GISTRAT	ION.	, and s	-	TY, STATE, ZIP CODE		,			-	

#### Important Information for Vehicle Owners

- Every person operating a motor vehicle shall have the Certificate of Registration for the motor vehicle and for the trailer, if any, and his/her license to operate, upon his/her person or in the vehicle, in some easily accessible place.
- By law, you must report any change of address to the RMV within 30 days in writing. Address changes can be made on the RMV website: www.massrmv.com or by mail to: RMV, P.O. Box 55889, Boston, MA 02205-5889. Once you have reported the address change to the RMV, please write corrected address in box provided above.
- Return the registration plates to the RMV immediately if:
- The vehicle has been sold or junked and the registration is not going to be transferred to another vehicle. Keep a copy of the Bill of Sale, Title, and completed Reassignment of Title for your records to document the transfer.
- You move to another state and you register the vehicle in that state.



 The insurance policy is not renewed or is cancelled and there is no plan to obtain a new policy.

Transferring Your Plates: Massachusetts law (M.G.L. Chapter 90, Section 2) allows you to transfer valid registration plates from this vehicle to a newly acquired new or used motor vehicle or trailer while you obtain insurance and a new registration. All the following must be met: 1. You are at least 18 years of age and you own the motor vehicle or trailer identified on this Registration Certificate. 2. You transfer ownership of this vehicle to another person or permanently lose possession of it (such as through repossession, etc.); 3. The newly acquired vehicle is of the same vehicle type (passenger vehicle to passenger vehicle, trailer to trailer etc.); the same registration type (passenger to passenger, commercial to commercial); and has the same number of wheels; and, 4. The seller and buyer properly complete the Assignment of the Certificate of Title (for the newly acquired "used" vehicle) or Certificate of Origin (if a "new" vehicle). If all the above are met, you may operate the newly acquired vehicle with the transferred plates up to 5:00 pm of the 7th calendar day following the date of transfer (or loss of possession). The day of transfer or loss is day #1. During that 7 days, you must carry the Bill of Sale (or the dealer's Purchase Contract) for the newly acquired vehicle and this Registration Certificate when operating the vehicle. See FAQs About the Seven-Day Registration Transfer Law on the RMV's website at www.massrmv.com.

No Insurance Card Required: Massachusetts's law does not require an Insurance card. The law, M.G.L. Chapter 90, Section 34A and Chapter 175, Section 113A requires the vehicle's owner to maintain a compulsory motor vehicle insurance policy or bond for bodily injury coverage and property damage insurance. If an insurer is identified on the face of this *Registration Certificate*, it is required by law to electronically notify the RMV (Registry of Motor Vehicles) if coverage lapses. The vehicle owner is then notified by the RMV to obtain new insurance within 10 days or the registration will be revoked. Bonds are filed with the State Treasurer's Office.

#### BE FIRST IN LINE BY GOING ONLINE AT WWW.MASSRMV.COM

Schedule a Road Test
Renew Your Driver's License
Renew Your Registration
Pay Citations/Court Hearing Fee
Replace Your Driver's License

Request a Duplicate Title
Request a Duplicate Registration
Change Your Address
Cancel My Plate/Registration

Order a Special Plate

NEED TO VISIT AN RMV OFFICE?

SAVE TIME Complete Your Application Online!

PAN	PASSENGER		09/01		kes it a crime to  EXPIRES LAST DAY OF		MONTH YEAR TRANS	92321300010051		
AFRS MODEL YEAR 2000 TOYT	ECHO	BODY STYLE/TYPE SEDAN	COLOR	REI			lid without official ture of Registrar	IF VEHICLE CARRYING PASSENGERS	TOTAL REGISTERED WEIGHT FOR A COMMERCIAL VEHICL	
TDBT1235Y0097  USIDENTIAL ADDRESS (IF DIFFERENT)	074 L	NCE COMPANY  IBERTY MUTU	JAL INS	TITLE NUME AV	332837	REGISTRAR		FOR HIRE: MAXIMUM NUMBER OF PASSENGERS	OR TRAILER.	
AME(S) OF OWNER(S) AND MAILING ADDRESS				X		Kach	el Kaprielian	SEATED.		
AND MAILING ADDRESS				A STATE		FEES	12.			
				4			REGISTRATION	50.0	0	
				. 00	11656		TITLE	0.0	0	
							SPECIAL PLATES	0.0	0	
							SALES TAX	0.00	0	
							TOTAL	50.0	0	
	REGIST	TTS DEPARTM RY OF MOTOR database constitute	VEHICLES	DIVIS	HOL		Au Sanag	1.00 mg		
PECIAL MESSAGE IF THIS VEHICLE IS NEWLY ACQUIRED, IT MUST BE INSPECTED WITHIN SEVEN (7)				CHAN	GE OF ADDRESS					
DAYS OF REGISTRATION.				STREET ADDRESS						
			-	STATE, ZIP CODE	1.	•				

- any, and his/her license to operate, upon his/her person or in the vehicle, in some easily accessible place.
- By law, you must report any change of address to the RMV within 30 days in writing. Address changes can be made on the RMV website: www.mass.gov/rmv or by mail to: RMV, P.O. Box 55889, Boston, MA 02205-5889. Once you have reported the address change to the RMV, please write corrected address in box provided above.
- The vehicle has been sold or junked and the registration is not going to be transferred to another vehicle. Keep a copy of the Bill of Sale, Title, and completed Reassignment of Title for your records to document the transfer.
- You move to another state and you register the vehicle in that state.



- The insurance policy is not renewed or is cancelled and there is no plan to obtain a new policy.

Transferring Your Plates: Massachusetts law (M.G.L. Chapter 90, Section 2) allows you to transfer valid registration plates from this vehicle to a newly acquired new or used motor vehicle or trailer while you obtain insurance and a new registration. All the following must be met: 1. You are at least 18 years of age and you own the motor vehicle or trailer identified on this Registration Certificate. 2. You transfer ownership of this vehicle to another person or permanently lose possession of it (such as through repossession, etc.); 3. The newly acquired vehicle is of the same vehicle type (passenger vehicle to passenger vehicle, trailer to trailer etc.); the same registration type (passenger to passenger, commercial to commercial); and has the same number of wheels; and, 4. The seller and buyer properly complete the Assignment of the Certificate of Title (for the newly acquired "used" vehicle) or Certificate of Origin (if a "new" vehicle). If all he above are met, you may operate the newly acquired vehicle with the transferred plates up to 5:00 pm of the 7th calendar day following he date of transfer (or loss of possession). The day of transfer or loss is day #1. During that 7 days, you must carry the Bill of Sale (or the dealer's Purchase Contract) for the newly acquired vehicle and this Registration Certificate when operating the vehicle. See FAQs About the Seven-Day Registration Transfer Law on the RMV's website at www.mass.gov/rmv.

Vo Insurance Card Required: Massachusetts's law does not require an Insurance card. The law, M.G.L. Chapter 90, Section 34A and Chapter 175, Section 113A requires the vehicle's owner to maintain a compulsory motor vehicle insurance policy or bond for bodily injury coverage and property damage insurance. If an insurer is identified on the face of this Registration Certificate, it is required by law to electronically notify the RMV (Registry of Motor Vehicles) if coverage lapses. The vehicle owner is then notified by the RMV to obtain new nsurance within 10 days or the registration will be revoked. Bonds are filed with the State Treasurer's Office.

# BE FIRST IN LINE BY GOING ONLINE AT WWW.MASS.GOV/RMV

Schedule a Road Test

Renew Your Driver's License

Renew Your Registration Pay Citations/Court Hearing Fee

Replace Your Driver's License

Request a Duplicate Title

Request a Duplicate Registration

Change Your Address

Cancel My Plate/Registration

Order a Special Plate

**NEED TO VISIT AN RMV OFFICE?** 

SAVE TIME Complete Your **Application Online!** 

PLATE TYPE PAN MFRS MODEL YEA.	120	PASSENGER	09/01	Cyce,	EXPIRES LAST DAY OF			RANSACTION NUMBER	900014046		
2000 VEHICLE IDENTIFIC	TOYT EC	CHO SEDAN	COLOR	REI			lid without official ture of Registrar	IF VEHICLE CARRYING PASSENGER	TOTAL REGISTERED WEIGHT FOR A COMMERCIAL VEHICLE		
THE R. P. LEWIS CO., LANSING, MICH.	1235Y0097074 DRESS (IF DIFFERENT)	(i) (ii) (iii) (ii		AV	332837	REGISTRAR		FOR HIRE: MAXIMUM NUMBER OF PASSENGERS THAT CAN BE	IS		
	N(S) AND MAILING ADDRESS	en de la				Nach	el Kaprielia	SEATED.			
	RE	HUSETTS DEPARTME	FHICLES	RANSP	ION		REGISTRATION TITLE SPECIAL PLATES SALES TAX TOTAL	0 . 0 . 0 .	.00		
PECIAL MESSAGE	The records of the	e RMV database constitute the	e official stat	tus of the	vehicle regist	ration.					
	IF THIS VEHICLE IS NEWLY ACQUIRED, IT MUST BE INSPECTED WITHIN SEVEN (7) DAYS OF REGISTRATION.				CHANGE OF ADDRESS  STREET ADDRESS						
					TATE, ZIP CODE						
		Important Inf	ormati	on fo	r Vehicl	e Ow	ners				
· Every pe	erson operating a m	notor vehicle shall have th	o Cortifi		eturn the regi						

- Every person operating a motor vehicle shall have the Certificate of Registration for the motor vehicle and for the trailer, if any, and his/her license to operate, upon his/her person or in the vehicle, in some easily accessible place.
- By law, you must report any change of address to the RMV within 30 days in writing. Address changes can be made on the RMV website: www.mass.gov/rmv or by mail to: RMV, P.O. Box 55889, Boston, MA 02205-5889. Once you have reported the address change to the RMV, please write corrected address in box provided above.
- Return the registration plates to the RMV immediately if:
- The vehicle has been sold or junked and the registration is not going to be transferred to another vehicle. Keep a copy of the Bill of Sale, Title, and completed Reassignment of Title for your records to document the transfer.
- You move to another state and you register the vehicle in that state.



 The insurance policy is not renewed or is cancelled and there is no plan to obtain a new policy.

Transferring Your Plates: Massachusetts law (M.G.L. Chapter 90, Section 2) allows you to transfer valid registration plates from this vehicle to a newly acquired new or used motor vehicle or trailer while you obtain insurance and a new registration. All the following must be met: 1. You are at least 18 years of age and you own the motor vehicle or trailer identified on this Registration Certificate. 2. You transfer ownership of this vehicle to another person or permanently lose possession of it (such as through repossession, etc.); 3. The newly acquired vehicle is of the same vehicle type (passenger vehicle to passenger vehicle, trailer to trailer etc.); the same registration type (passenger to passenger, commercial to commercial); and has the same number of wheels; and, 4. The seller and buyer properly complete the Assignment of the Certificate of Title (for the newly acquired "used" vehicle) or Certificate of Origin (if a "new" vehicle). If all the date of transfer (or loss of possession). The day of transfer or loss is day #1. During that 7 days, you must carry the Bill of Sale (or the Seven-Day Registration Transfer Law on the RMV's website at <a href="https://www.mass.gov/rmv">www.mass.gov/rmv</a>.

No Insurance Card Required: Massachusetts's law does not require an Insurance card. The law, M.G.L. Chapter 90, Section 34A and Chapter 175, Section 113A requires the vehicle's owner to maintain a compulsory motor vehicle insurance policy or bond for bodily injury coverage and property damage insurance. If an insurer is identified on the face of this *Registration Certificate*, it is required by law to electronically notify the RMV (Registry of Motor Vehicles) if coverage lapses. The vehicle owner is then notified by the RMV to obtain new nsurance within 10 days or the registration will be revoked. Bonds are filed with the State Treasurer's Office.

# BE FIRST IN LINE BY GOING ONLINE AT WWW.MASS.GOV/RMV

Schedule a Road Test

Renew Your Driver's License Renew Your Registration

Pay Citations/Court Hearing Fee Replace Your Driver's License Request a Duplicate Title

Request a Duplicate Registration

Change Your Address

Cancel My Plate/Registration

Order a Special Plate

**NEED TO VISIT AN RMV OFFICE?** 

SAVE TIME
Complete Your
Application Online!

Commonwealth of Massachusetts Motor Vehicle Inspection and Maintenance Program

**PASS** 

PASS

**PASS** 

**PASS** 

PASS

Air Bags

Windshield

Fuel Tank Filler Cap

Altered Vehicle Height

# Vehicle Inspection Report



Please Review This Important Information

Your vehicle has PASSED its SAFETY TEST. The results are summarized in this report.

Questions? Visit www.mass.gov/vehiclecheck or call Customer Service at 1-844-358-0135. Customer Service is staffed from 7 a.m. to 5 p.m. Monday, Wednesday, Friday, and Saturday, and from 7 a.m. to 8 p.m. on Tuesday and Thursday.

Overall Result:	PASS		Vehicle Informa	ation		Station Information	
Safety Result Emissions Result Start Test Date/Time End Test Date/Time Test Type	PASS N/A 2/27/2018 2/27/2018 Regular	8:27 AM	VIN License Plate Plate Type/State Vehicle Type Year / Make	JTDBT1235	Y0097074	NDRN INC. DBA X & L'S SE 191 ESSEX ST	ER
Sticker Number Inspection Type Inspection Counter	190802196 Retest 2	8	Model Fuel Type Engine Cyl / Size GVWR Odometer	ECHO GASOLINE 4 / 1.5L 8500 40315			F
Safety Inspection R	esults					Inspection Fee	\$0.00
license Plate Mounting a florn lighting Devices and Ref Reering and Suspension	lectors	PASS PASS PASS	Service Brakes Stop Lights and Tail L Directional Signals an Frame		PASS PASS PASS PASS	Parking Brake Headlight Aim and Operation Front End Windshield Wipers and Cleaner	PASS PASS PASS PASS
Safety Belts		DACC	Air Dans			This of the state	FA35

**PASS** 

**PASS** 

**PASS** 

**PASS** 

nspection Comments

Sumpers/Fenders/Exterior Sheet Metal

lone

Safety Belts

Vindow Tint

'isible Smoke

Scan to visit website

**PASS** 

PASS

**PASS** 

**PASS** 

Muffler and Exhaust System

Fuel Tank Filler Neck and Components

Rear View Mirror







#### Please Review This Important Information

Your vehicle has FAILED its SAFETY TEST. Here is what you need to do now:

\* Fix safety defects immediately. Do not drive your vehicle until repairs are made.

\* Have your repaired vehicle re-tested within 60 days of your initial inspection. The first re-test is free at the original inspection station during this period. If your vehicle does not pass a re-test within 60 days of its initial inspection, RMV may suspend your registration.

If you have questions about your vehicle's inspection, please visit www.mass.gov/vehiclecheck or call Customer Service at 1-844-358-0135. Customer Service is staffed from 7 a.m. to 5 p.m. Monday, Wednesday, Friday, and Saturday, and from 7 a.m. to 8 p.m. on Tuesday and Thursday.

Overall Result:	FAIL		Vehicle Information			Station Information		
Safety Result	FAIL		VIN	JTDBT1235	Y0097074	NDRN INC. DBA X & L'S SER		
Emissions Result	N/A		License Plate			NEKKI INO. BBA X & ES SEK		
Start Test Date/Time	2/24/2018	3:32 PM	Plate Type/State					
	2/24/2018 3		Vehicle Type	_	R			
	Regular		Year / Make					
	190802185		Model	2000 Toyota				
	Initial			ECHO				
	1		Fuel Type	GASOLINE		Workstation Number M	IAW00000123	
inspection Counter			Engine Cyl / Size	4 / 1.5L		Inspector Number	*****0681	
			GVWR	8500				
			Odometer	40315				
Safaty Inamastica Ba						Inspection Fee	\$35.00	
Safety Inspection Res License Plate Mounting and		PASS	Service Brakes		PASS	Darking Dunka	7100	
Horn		PASS	Stop Lights and Tail L	ights	PASS	Parking Brake Headlight Aim and Operation	PASS	
ighting Devices and Refle	ectors	PASS	Directional Signals and		PASS	Front End	PASS FAIL	
Steering and Suspension		PASS	Frame		PASS	Windshield Wipers and Cleaner	PASS	
Safety Belts		PASS	Air Bags		PASS	Muffler and Exhaust System	PASS	
Nindow Tint		PASS	Windshield		PASS	Rear View Mirror	PASS	
3umpers/Fenders/Exterior	Sheet Metal	PASS	Fuel Tank Filler Cap		PASS	Fuel Tank Filler Neck and Components		
/isible Smoke		PASS	Altered Vehicle Height	t	PASS	Tires	PASS	
Other		PASS						
nspection Comments	S							

Scan to visit website



/IR Number

**3ROKEN SPRING** 







## Please Review This Important Information

Congratulations. Your vehicle has PASSED its SAFETY TEST. The results are summarized in this report.

Questions? Visit www.mass.gov/vehiclecheck or call the Motorist Hotline at 1-866-941-6277. The Hotline is staffed from 7 a.m. to 5 p.m. Monday, Wednesday, Friday, and Saturday, and from 7 a.m. to 8 p.m. on Tuesday and Thursday.

Pass	Vehicle Information	n	Station Information		
Pass N/A 9/3/2015 12:00:44PM Regular 163017228 Initial 1	VIN License Plate Plate Type/State Vehicle Type Year / Make Model Fuel Type GVWR Odometer	JTDBT1235Y0097074  2000 TOYOTA ECHO Gasoline 8500 37447		ETROLEUM INC	
k Pass Pass Pass Pass	Exhaust Check Rear View Mirror Check	Pass Pass	Horn Check Lighting/Reflector Check Suspension Check Safety Belts Check Window Tint Check Bumpers/Fenders Check Visible Smoke Check Parking Brake Check	Pass Pass Pass Pass Pass Pass Pass Pass	
1	Pass N/A 9/3/2015 12:00:44PM Regular 163017228 Initial 1  Results  Pass Pass Pass Pass Pass Pass Pass P	Pass VIN N/A License Plate 9/3/2015 Plate Type/State 12:00:44PM Vehicle Type Regular Year / Make 163017228 Model Initial Fuel Type 1 GVWR Odometer  Results  Pass Service Brakes Headlamp Check Pass Headlamp Check Pass Wipers and Cleaner Check Pass Exhaust Check Pass Rear View Mirror Check Pass Fuel Tank Fill Neck Check Pass Tires Check Pass Tires Check Pass	Pass VIN JTDBT1235Y0097074  N/A License Plate  9/3/2015 Plate Type/State  12:00:44PM Vehicle Type  Regular Year / Make 2000 TOYOTA  163017228 Model ECHO  Initial Fuel Type Gasoline  1 GVWR 8500  Odometer 37447   Results  Pass Service Brakes Pass  neck Pass Headlamp Check Pass ek Pass Frontend Check Pass Pass Wipers and Cleaner Check Pass Pass Exhaust Check Pass Pass Rear View Mirror Check Pass Pass Pass Fuel Tank Fill Neck Check Pass Pass Pass Tires Check Pass Pass Pass Tires Check Pass	Pass VIN JTDBT1235Y0097074 Name: AMERICAN PE Address: 586 CABOT S' BEVERLY, MA 978-922-9749  Regular Year / Make 2000 TOYOTA  163017228 Model ECHO Initial Fuel Type Gasoline Station Number  1 GVWR 8500 Workstation Number  1 GVWR 8500 Workstation Number Inspector Number Test Fee  Results  Results  Pass Service Brakes Pass Horn Check Pass Lighting/Reflector Check Pass Suspension Check Pass Safety Belts Check Pass Safety Belts Check Pass Rear View Mirror Check Pass Window Tint Check Pass Fuel Tank Fill Neck Check Pass Visible Smoke Check Pass Tires Check Pass Tires Check Pass Parking Brake Check Pass Parking Brake Check Pass Tires Check Pass Parking Brake Check	



#### Please Review This Important Information

Congratulations. Your vehicle has PASSED both its SAFETY TEST and its EMISSIONS TEST. The results are summarized in this report.

Questions? Visit www.mass.gov/vehiclecheck or call the Motorist Hotline at 1-866-941-6277. The Hotline is staffed from 7 a.m. to 5 p.m. Monday, Wednesday, Friday, and Saturday, and from 7 a.m. to 8 p.m. on Tuesday and Thursday.

Overall Result: Pass		Vehicle Information			Station Information				
Safety Result	Pass		VIN	JTDBT12	35Y0097074	Name:	AMERICAN P	ETROLEUM INC	
Emissions Result	Pass		License Plate	376LP8		Address	586 CABOT S	T	
Test Date	10/23/2012		Plate Type/State	PAN / MA			BEVERLY, MA		
Test Time	2:24:57PM		Vehicle Type	Passenge			978-922-9749		
Test Type	Regular		Year / Make	2000 TOY			010 022 0140		
Sticker Number	134311605		Model	ECHO					
Inspection Type	Initial		Fuel Type	Gasoline		Station N	lumber	PB020770	
Inspection Count	1		Engine Cyl/Size	4/ 1.5			tion Number	ST000796	
			GVWR	8500			r Number	****2490	
Safaty Inamasticus	Dagulta		Odometer	33224		Test Fee		\$29.00	
Safety Inspection	Results			00221				Ψ20.00	
Visual Plate Check		Pass	Service Brakes		Pass	Horn Check		Pass	
Stop and Tail Lights C		Pass	Headlamp Check		Pass	Lighting/Refle	ctor Check	Pass	
Directional Lights Che	ck	Pass	Frontend Check		Pass	Suspension C	check	Pass	
Frame Check		Pass	Wipers and Cleaner Che	ck	Pass	Safety Belts C	Check	Pass	
Air Bags Check		Pass	Exhaust Check		Pass	Window Tint (	Check	Pass	
Windshield Check		Pass	Rear View Mirror Check		Pass	Bumpers/Fen	ders Check	Pass	
Fuel Tank Fill Cap Che	eck	Pass	Fuel Tank Fill Neck Chec	k	Pass	Visible Smoke	Check	Pass	
Vehicle Height Check		Pass	Tires Check		Pass	Parking Brake	Check	Pass	
Other		Pass							
Safety Inspection	Comments								

#### On-Board Diagnostic (OBD) Test Results

OBD Tampering Check	Pass	OBD Connector Result	Pass	OBD MIL Status Result	Pass
OBD Key-On Bulb Check	N/A	<b>OBD Communication Result</b>	Pass	<b>OBD Readiness Monitor Result</b>	Pass
OBD Engine-Running Bulb Check	N/A	OBD RPM Check	Pass	OBD Test QA Check	
OBD Scan Tool Check Result	N/A	Pin 16 Volts Check	13.8		

#### On-Board Diagnostic (OBD) Monitor Results

Catalyst Monitor Ready
Catalyst Heater Monitor Not Supported





## Please Review This Important Information

Congratulations. Your vehicle has PASSED both its SAFETY TEST and its EMISSIONS TEST. The results are summarized in this report.

Questions? Visit www.mass.gov/vehiclecheck or call the Motorist Hotline at 1-866-941-6277. The Hotline is staffed from 7 a.m. to 5 p.m. Monday, Wednesday, Friday, and

Safety Result Pass Emissions Result Pass Fest Date 9/15/2010 Fest Time 10:25:11. Fest Type Regular Sticker Number 1143316: Inspection Type Initial Inspection Count 1  Safety Inspection Results Fisual VIN Check Pation Check Pationspension Ch	AM Vehicle Year / M 18 Model Fuel Ty	e Plate Sype/State e Type  Make  2000 TOY ECHO Gasoline Cyl/Size  4/ 1.5	P35Y0097074 Name: Addres  YOTA Station	SS: 586 CABOT ST BEVERLY, MA 0 978-922-9749 Number	
risual VIN Check Pa Horn Check Pa Lighting/Reflector Check Pa Suspension Check Pa Safety Belts Check Pa	Odome		Inspect Test Fe	ation Number for Number see	ST000796 ****6943 \$29.00
lumpers/Fenders Check Parisible Smoke Check	Stop an Direction Siss Direction Siss Frame (Siss Air Bags Windships Fuel Tailss Vehicle Siss Other Ints	Plate Check Pas and Tail Lights Check Pas check Pas s Check Pas ield Check Pas ank Fill Cap Check Pas Height Check Pas	Headlam SS Frontend SS Wipers at SS Exhaust ( SS Rear View SS Fuel Tank SS Tires Che	p Check Check Ind Cleaner Check Check W Mirror Check K Fill Neck Check	Pass Pass Pass Pass Pass Pass Pass Pass

BD Tampering Check BD Key-On Bulb Check	Pass N/A	OBD Connector Result OBD Communication Result	Pass Pass	OBD MIL Status Result OBD Readiness Monitor Result	Pass Pass	
BD Engine-Running Bulb Check	N/A	OBD RPM Check	Pass	OBD Test QA Check		
BD Scan Tool Check Result	N/A	Pin 16 Volts Check	13.8			

## n-Board Diagnostic (OBD) Monitor Results

atalyst Monitor Ready atalyst Heater Monitor Mat Cumantad





#### Please Review This Important Information

Congratulations. Your vehicle has **PASSED** both its **SAFETY TEST** and its **EMISSIONS TEST**. The results are summarized in this report.

Questions? Visit **www.mass.gov/vehiclecheck** or call the **Motorist Hotline** at **1-866-941-6277**. The Hotline is staffed from 7 a.m. to 5 p.m. Monday, Wednesday, Friday, and Saturday, and from 7 a.m. to 8 p.m. on Tuesday and Thursday.

Overall Result:	Pass	Vehicle Information		Station Information	
Safety Result	Pass	VIN	TDBT1235Y0097074	Name: IRA TOYOTA	
Emissions Result	Pass	License Plate		Address: 161B ANDOVE	RSTREET
Test Date	10/13/2009	Plate Type/State	al a	DANVERS, MA	
Test Time	12:06:13PM	Vehicle Type	8.1	978-739-8333	101323
Test Type	Regular	Voor / Mala	OUU TUYUTA	070-700-0000	
Sticker Number	107860127		СНО		
Inspection Type	Initial		Sasoline	Station Number	PB004934
Inspection Count	1		/ 1.5	Workstation Number	ST000511
			500	Inspector Number	****7026
Safety Inspection Results		Odometer 2	7652	Test Fee	\$29.00
Visual VIN Check	Pass	Visual Plate Check	Pass	Service Brakes	Pass
Horn Check	Pass	Stop and Tail Lights Chec		Headlamp Check	Pass
Lighting/Reflector Chec	k Pass	Directional Lights Check	Pass	Frontend Check	Pass
Suspension Check	Pass	Frame Check	Pass		
Safety Belts Check	Pass	Air Bags Check	Pass	Exhaust Check	Pass
Window Tint Check	Pass	Windshield Check	Pass	Rear View Mirror Check	Pass
Bumpers/Fenders Ched	ck Pass	Fuel Tank Fill Cap Check	Pass		Pass
Visible Smoke Check	Pass	Vehicle Height Check	Pass	Tires Check	Pass
Parking Brake Check	Pass	Other	Pass		
Safety Inspection	Comments				

## On-Board Diagnostic (OBD) Test Results

ODD T . OL .						
OBD Tampering Check	Pass	OBD Connector Result	Pass	OBD MIL Status Result	Pass	
OBD Key-On Bulb Check	NI/A	000 0 : " 5 "				
ODD Ney-OH Build Check	N/A	OBD Communication Result	Pass	OBD Readiness Monitor Result	Pass	
OBD Engine-Running Bulb Check	N/A	OPD DDM Charle			1 400	
	IN/A	OBD RPM Check	Pass	OBD Test QA Check		
OBD Scan Tool Check Result	N/A					
D1 4014 H 21						
Pin 16 Volts Check	14 0					

#### On-Board Diagnostic (OBD) Monitor Results

Catalyst Monitor

Daad.